



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

OCT 13 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Attn: Document Control Desk

SALEM GENERATING STATION
LICENSE NO. DPR-75
DOCKET NO. 50-272
UNIT NO. 1

LICENSEE EVENT REPORT NO. 95-020-00

This Licensee Event Report entitled "Inoperable 230 Volt Motor Control Centers Due to Failed Bus Bar Bolting" is being submitted pursuant to the requirements of the Code of Federal Regulations 10CFR50.73(a)(2)(ii)(B). Attachment A contains those commitments which are currently outstanding related to this issue.

Sincerely,

Clay C. Warren
General Manager -
Salem Operations

Attachment A
SORC Mtg. 95-116

JMO

C Distribution
LER File

130103

The power is in your hands.

9510200220 951013
PDR ADOCK 05000272
S PDR

Attachment A

PSE&G Commitments for LER 272/95-020

The following item represents PSE&G commitments made to the Nuclear Regulatory Commission related to LER 272/95-020. The commitments are as follows:

1. A design change package (DCP) (DCP-1ER-0098) was developed for Unit #1 Vital 230 Volt MCCs to replace all bus bolts with carbon steel bolts. The DCP will be completed by December 31, 1995.
2. Non Vital bus bolt replacement for Unit #1 will be completed by December 31, 1995.
3. Non Vital Bus bolt replacement for Unit #2 will be completed by March 31, 1996.
4. Improve the Operating Experience Program (OEP) by March 31, 1996 to ensure that action items coming from industry events are addressed and closed in a timely manner.