

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:
Mr. Norman C. Moseley

FROM:
Florida Power & Light Company
Miami, Florida
A. D. Schmidt

DATE OF DOCUMENT
6/18/76

DATE RECEIVED
7/6/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP INPUT FORM

NUMBER OF COPIES RECEIVED
No original

DESCRIPTION

Ltr. Trans the following:

ENCLOSURE

Licensee Event Report (RO 50-335/76-21) on 5/18/76 concerning the "A" diesel generator being placed out of service.

ACKNOWLEDGED

DO NOT REMOVE

(1-P) (2-P)

PLANT NAME:

St. Lucie #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

7/6/76

RJL

<input checked="" type="checkbox"/>	BRANCH CHIEF:	Ziemann		
	W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/>	LIC. ASST:	Diggs		
	W/1 CYS			
	ACRS 16 CYS HOLDING/SENT TO LA			

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	REG FILE			
<input checked="" type="checkbox"/>	NRC PDR			
<input checked="" type="checkbox"/>	I & E (2)			
<input checked="" type="checkbox"/>	MIPC (3)			
<input checked="" type="checkbox"/>	SCHROEDER/IPPOLITO			
<input checked="" type="checkbox"/>	HOUSTON			
<input checked="" type="checkbox"/>	NOVAK/CHECK			
<input checked="" type="checkbox"/>	GRIMES			
<input checked="" type="checkbox"/>	CASE			
<input checked="" type="checkbox"/>	BUTLER			
<input checked="" type="checkbox"/>	HANAUER			
<input checked="" type="checkbox"/>	TEDESCO/MACCARY			
<input checked="" type="checkbox"/>	EISENHUT			
<input checked="" type="checkbox"/>	BAER			
<input checked="" type="checkbox"/>	SHAO			
<input checked="" type="checkbox"/>	VOLLMER/BUNCH			
<input checked="" type="checkbox"/>	KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/>	LPDR: Ft. Pierce, Fla.			
<input checked="" type="checkbox"/>	TIC			
<input checked="" type="checkbox"/>	NSIC			

6698

10-1

10-1

10-1

10-1

10-1

10-1

10-1

10-1

10-1



50-885 15-COPIES

June 18, 1976

PRN-LI-76-149

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-21
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MAY 18, 1976

"A" DIESEL GENERATOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.



Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement. (30)
Director, Office of Management Information and
Program Control (3)



Regulatory Docket File

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 F L S L S 1 | LICENSE NUMBER: 0 0 - 0 0 0 0 0 0 - 0 0 | LICENSE TYPE: 4 1 1 1 1 | EVENT TYPE: 0 3

CATEGORY: 01 CONT | REPORT TYPE: L | REPORT SOURCE: L | DOCKET NUMBER: 0 5 0 - 0 3 3 5 | EVENT DATE: 0 5 1 8 7 6 | REPORT DATE: 0 6 1 8 7 6

EVENT DESCRIPTION

02 | During preoperational testing, the "A" diesel generator was being tested
03 | to verify operability when one of the air start system solenoid valves
04 | and its associated air line were found to be clogged with dirt. The "A"
05 | diesel generator was placed out of service so that the valve and air
06 | line could be cleaned. During this time, the "B" diesel generator was

SYSTEM CODE: E E | CAUSE CODE: E | COMPONENT CODE: E N G I N E | PRIME COMPONENT SUPPLIER: A | COMPONENT MANUFACTURER: E 1 4 7 | VIOLATION: N

CAUSE DESCRIPTION

08 | The "A" diesel generator was placed out of service to clean a clogged
09 | air start system solenoid valve and air line. They were cleaned in
10 | accordance with the manufacturer's guidelines. The manufacturer's

FACILITY STATUS: B | % POWER: 0 0 0 | OTHER STATUS: N/A | METHOD OF DISCOVERY: a | DISCOVERY DESCRIPTION: N/A

FORM OF ACTIVITY RELEASED: Z | CONTENT OF RELEASE: Z | AMOUNT OF ACTIVITY: N/A | LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES

NUMBER: 0 0 0 | TYPE: Z | DESCRIPTION: N/A

PERSONNEL INJURIES

NUMBER: 0 0 0 | DESCRIPTION: N/A

PROBABLE CONSEQUENCES

15 | N/A

LOSS OR DAMAGE TO FACILITY

TYPE: Z | DESCRIPTION: N/A

PUBLICITY

17 | N/A

ADDITIONAL FACTORS

18 | See Page Two for continuation of Event Description and Cause Description.


19 |

Event Description (continued)

verified operable in accordance with Technical Specification 3.8.1.1. The problem was corrected and the "A" diesel generator was started and verified operable. This was the first occurrence of this type. (335-76-21).

Cause Description (continued)

maintenance manual for the diesel generator does not specify a frequency for cleaning components except to say that cleaning should be scheduled as determined by operating conditions. Cleaning of the affected components is being incorporated in the preventive maintenance program.



June 18, 1976

PRN-LI-76-149

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-21
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MAY 18, 1976

"A" DIESEL GENERATOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment


cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

6755

A 0 4

JUN 21 10 35 AM '76

REGISTRATION
OPERATIONS
ALABAMA



REPORTABLE OCCURRENCE 335-76-21
LICENSEE EVENT REPORT
PAGE TWO

Event Description (continued)

verified operable in accordance with Technical Specification 3.8.1.1. The problem was corrected and the "A" diesel generator was started and verified operable. This was the first occurrence of this type. (335-76-21).

Cause Description (continued)

maintenance manual for the diesel generator does not specify a frequency for cleaning components except to say that cleaning should be scheduled as determined by operating conditions. Cleaning of the affected components is being incorporated in the preventive maintenance program.