

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: System Sensor Division Honeywell International, Inc. 3825 Ohio Avenue St. Charles, Illinois 60174 REPORT NUMBER(S) 2018001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-08445	4. LICENSE NUMBER(S) 12-15023-02E	5. DATE(S) OF INSPECTION 03/28/2018 to 5/09/2018
--------------------------------------	--	---

6. INSPECTION PROCEDURES USED 87125	7. INSPECTION FOCUS AREAS 03.01-03.08
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03251	2. PRIORITY 5	3. LICENSEE CONTACT David Nemeth	4. TELEPHONE NUMBER (630) 762-5293
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: March 28, 2023

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an unannounced, routine inspection of a licensee that imported sealed sources containing less than one microcurie each of americium-241, installed the sources in smoke detectors, and then distributed the products to persons exempt from NRC or Agreement State regulations. At the time of the inspection, the licensee was authorized to distribute smoke detectors from two locations. The St. Charles, IL location stopped all activities related to the manufacture and distribution of smoke detectors containing radioactive material in 2015, and the Juarez, Mexico location stopped similar activities on 2009. The licensee informed the inspector of its intent to terminate the license.

PERFORMANCE OBSERVATIONS

The inspector reviewed the licensee's annual exempt distribution reports through 2015. The inspector also reviewed decommissioning documents for the Juarez, Mexico facility as part of the in-office review because these records were not immediately available during the onsite inspection. The inspector and the licensee staff discussed the license termination process and requirements.

No violations of NRC requirements were identified as a result of this inspection.

Nieves Folch, Luis

From: Nieves Folch, Luis
Sent: Thursday, May 10, 2018 8:51 AM
To: 'Nemeth, David (IL14)'; 'Jeremy Kieser'
Subject: NRC clear 591 report
Attachments: SKM_C45818051009280.pdf

Dear Mr. Nemeth and Mr. Kiesser,

Attach is the clear 591 report for the inspection conducted on March 28, 2018, as discussed on the exit meeting here is the contact information on some of the people in Head Quarters you want to contact to terminate your license Richard K. Struckmeyer, Materials Safety Licensing Branch, 301-415-5477 Richard.Struckmeyer@nrc.gov and Xu, Shirley, Material Safety Licensing, 301-415-7640 Xu, Shirley.Xu@nrc.gov .

In accordance with Title 10 of the Code of Federal Regulations 2.390 of the NRC's "Rules of Practice," a copy of this message will be available electronically for public inspection in the NRC's Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC's website at <http://www.nrc.gov/reading-rm/adams.html>.

Please feel free to contact me if you have any questions regarding this correspondence.

Thank you,

Luis Nieves
Health Physicist
U.S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
Office: (630) 829-9571
Fax: (630) 515-1259