

8005120 394

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

May 9, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 255E/031480  
NO/RMT:baw  
Pocket Nos. 50-280  
50-281  
License Nos. DPR-32  
DPR-37

Dear Mr. O'Reilly:

VEPCO letter, serial no. 255/031480 dated April 7, 1980, responded to non-compliances cited in IE Inspection Report nos. 50-280/80-1 and 50-281/80-3. The attached supplemental response to infraction P regarding inadequate procedures is forwarded as requested.

Very truly yours,

ORIGINAL SIGNED BY  
B. R. SYLVIA

B. P. Sylvia  
Manager-Nuclear Operations  
and Maintenance

Attachment

cc: Mr. Albert Schwencer

A001  
s  
//

Attachment

Supplemental Response to Inspection  
Report Nos. 50-280/80-1 and  
50-281/80-3

2.) Corrective steps to avoid further deficiencies:

A detailed review of station valve line-ups is being conducted and additions or corrections to upgrade the line-ups are being made as necessary. Additionally a MOP (Maintenance Operating Procedure) review is underway to insure valves addressed in removing systems or components from service are also addressed in returning them to service. Generic Maintenance Operating Procedures will also be upgraded to address this potential problem.

3.) Date when full compliance will be achieved:

The review of valve line-ups and MOP upgrading will be completed by June 30, 1980.