

50-244

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: J.P.O. Reilly

FROM: Rochester Gas & Elec Corp.
Rochester, N.Y.
L.D. White, Jr.

DATE OF DOCUMENT

4-23-76

DATE RECEIVED

4-26-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

30

DESCRIPTION

Ltr. trans the following.....

ENCLOSURE

Licensee Event Report (R.O. # 76-12/3L- 30 day report) on 3-31-76 Concerning Containment personnel airlock handwheel shaft seal excessive leakage during testing.....

(30 Carbon Cys. Received)

DO NOT REMOVE
ACKNOWLEDGED

PLANT NAME: RE Ginna # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 4-28-76

BRANCH CHIEF:

Purpose

W/3 CYS FOR ACTION

LIC. ASST:

Sheppard

W/ CYS

ACRS 16 CYS ~~HOLDING~~ SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/SCHWENCER

CASE

F. WILLIAMS

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Lyons & Rochester, N.Y.

TIC

NSIC

4169



1

...

...

...

...

...

...

...




Regulatory Docket File



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT



TELEPHONE
AREA CODE 716 546-2700

April 23, 1976



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-12 (30-day report), Containment
personnel airlock handwheel shaft seal excessive leakage
during testing
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:


In accordance with Technical Specifications, Article 6.9.2b, the attached
report of Reportable Occurrence 76-12 (30-day) is hereby submitted. Two
additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)



LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] []
1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME [01] N Y R E G I						LICENSE NUMBER [] [] - [] [] [] [] [] [] - [] []						LICENSE TYPE [4] [1] [1] [1] [1]				EVENT TYPE [0] [3]	
7	8	9	14	15	25	26	30	31	32								

CATEGORY [01] CONT		REPORT TYPE [L]	REPORT SOURCE [L]	DOCKET NUMBER [0] [5] [0] - [0] [2] [4] [4]				EVENT DATE [0] [3] [3] [1] [7] [6]			REPORT DATE [0] [4] [2] [3] [7] [6]		
7	8	57	58	59	60	61	68	69	74	75	80		

EVENT DESCRIPTION

[02] During routine 60 psig pressure decay test of personnel hatch air lock excessive leakage
 [03] was observed from an outer door handwheel shaft packing. Leakage from an air lock
 [04] shaft packing was previously reported 3/30/70. The packing nut was threaded back in
 [05] packing gland and tightened. The airlock volume was retested satisfactorily with no
 [06] adjustment required on the redundant door. (Reportable Occurrence 76-12, 30-day)

SYSTEM CODE [07] Z Z	CAUSE CODE [F]	COMPONENT CODE [Z] [Z] [Z] [Z] [Z] [Z]	PRIME COMPONENT SUPPLIER [Z]	COMPONENT MANUFACTURER [Z] [9] [9] [9]	VIOLATION [N]					
7	8	9	10	11	12	17	43	44	47	48

CAUSE DESCRIPTION

[08] The shaft packing nut backed off due to repeated door operation during concentrated
 [09] maintenance efforts during the refueling outage. Action to prevent recurrence is being
 [10] investigated.

FACILITY STATUS [11] H	% POWER [0] [0] [0]	OTHER STATUS NA	METHOD OF DISCOVERY [b]	DISCOVERY DESCRIPTION NA					
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED [12] Z	CONTENT OF RELEASE [Z]	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA				
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER [13] 0 0 0	TYPE [Z]	DESCRIPTION NA				
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER [14] 0 0 0	DESCRIPTION NA				
7	8	9	11	12	80

OFFSITE CONSEQUENCES

[15] NA

LOSS OR DAMAGE TO FACILITY

TYPE [16] Z	DESCRIPTION NA			
7	8	9	10	80

PUBLICITY

[17] NA

ADDITIONAL FACTORS

[18] NA

[19]

NAME: Charles V. Hartlieb PHONE: 716/546-2700, ext. 291-216