



2006  
MAY 10 2006

RECEIVED  
MAY 10 2006  
MAY 10 2006

.....

.....

( )  
( )

.....

.....

.....

.....

.....

.....

.....

.....



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

November 9, 1976



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-25 (30-day report), Leak at Residual Heat Removal System return pipe vent  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:


In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-25, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)  
Mr. William G. McDonald (3)





LER 76-25/3L  
**LICENSEE EVENT REPORT**

Regulatory Docket File

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

Received w/Ltr Dated: 11-9-76

LICENSEE NAME: 01 N Y R E G I LICENSE NUMBER: 00-000000-00 LICENSE TYPE: 41111 EVENT TYPE: 03

CATEGORY: 01 CONT 57 REPORT TYPE: L 59 REPORT SOURCE: L 60 DOCKET NUMBER: 050-0244 68 EVENT DATE: 101076 74 REPORT DATE: 110976 80

EVENT DESCRIPTION

02 | During operation of RHR system an operator noted small puddle on floor and discovered  
03 | leak at weldolet to nipple weld on 3/4" vent on RHR return line. This is similar to  
04 | Reportable Occurrence 74-5. Replaced nipple and rewelded using approved procedures.  
05 | (Reportable Occurrence 76-25, 30-day).  
06 |

SYSTEM CODE: CF CAUSE CODE: B COMPONENT CODE: PIPEXX PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: K055 VIOLATION: N

CAUSE DESCRIPTION

08 | Stresses were induced due to improper fitup of nipple to socket during construction.  
09 | Nipple appeared bottomed in socket. New nipple properly installed.  
10 |

FACILITY STATUS: G % POWER: 000 OTHER STATUS: NA METHOD OF DISCOVERY: a DISCOVERY DESCRIPTION: By operator

FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 | NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z DESCRIPTION: NA

PUBLICITY

17 | NA

ADDITIONAL FACTORS

18 | NA

19 |

NAME: Jack Noon PHONE: 716/546-2700, ext. 291-215

