

LER 76-16/3L
LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	R	E	G	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3						
7	8	9				14	15									25	26				30	31	32							
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE				REPORT DATE								
01						L	L	0	5	0	-	0	2	4	4	0	5	2	0	7	6	0	6	0	4	7	6			
7	8			57	58	59	60	61							68	69					74	75					80			

EVENT DESCRIPTION

02 | During check of computer rod position program, rod position deviation channel was found
 03 | to be inoperable. A hand log was started as specified by Tech.Spec. Table 3.5-1, Item
 04 | 16a. Item 16b was still in service. Computer technician re-initialized program and rod
 05 | position program check was completed satisfactorily. The channel was deemed operable
 06 | and the hand log terminated. (Reportable Occurrence 50-244/76-16, 30-day).

SYSTEM CODE				CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
07	I	F		E	I	N	S	T	R	U	N	W	1	2	0	N	
7	8	9	10	11	12					17	43	44			47	48	

CAUSE DESCRIPTION

08 | The event was caused by a failure in the computer to correctly monitor rod position
 09 | deviation. Upon re-initializing, the computer program was again found operable.
 10 | Operator verification of Tech.Spec.-related programs in the (cont'd. on attached sheet)

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	E	1	0	0	NA	b	NA								
7	8	9	10	11	12	13	44	45	46					80	

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE				
12	Z	Z	NA	NA									
7	8	9	10	11	44	45							80

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION					
13	0	0	0	Z	NA					
7	8	9	11	12	13					80

PERSONNEL INJURIES

NUMBER			DESCRIPTION							
14	0	0	0	NA						
7	8	9	11	12						80

OFFSITE CONSEQUENCES

15	NA									
7	8	9								80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION								
16	Z	NA								
7	8	9	10							80

PUBLICITY


17	NA									
7	8	9								80

ADDITIONAL FACTORS

18 | Corrective Action Report 1080 has been initiated for this event.

19										
7	8	9								80

NAME: Thomas A. Meyer PHONE: 716/546-2700, ext. 291-206



Licensee Event Report
Reportable Occurrence 50-244/76-16

Cause Description (cont'd.)

computer will be continued, and a Tech. Spec. change will be considered to eliminate further reports of this event when a suitable alternative is in effect.