

**NRC CONTRIBUTION FOR PART 50 DOCKET MATERIAL**  
(TEMPORARY FORM)

CONTROL NO: 13583  
FILE: INCIDENT REPORT FILE

FROM: Rochester Gas & Elec. Co Rochester, N.Y. L.D. White, Jr.		DATE OF DOC 12-2-75	DATE REC'D 12-4-75	LTR XXX	TWX	RPT	OTHER
TO: James P.O'Reilly		ORIG None	CC 3	OTHER	SENT AEC PDR SENT LOCAL PDR		XXX XXX
CLASS	UNCLASS EXX	PROP INFO	INPUT	NO CYS REC'D 3	DOCKET NO: 50-244		

DESCRIPTION: Letter trans the following.....	ENCLOSURES: Unusual Event Report #. 75-10, on 11-6-75, Concerning a Unresponsive Emergency Generator Governor..... W/Attachment.....  (3 Cys. Received)
---	--

PLANT NAME: RE Ginna # 1

**FOR ACTION/INFORMATION**

SAB 12-5-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/3 Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

**ACKNOWLEDGED**  
**DO NOT REMOVE**

**INTERNAL DISTRIBUTION**

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER  ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ  PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	---

**EXTERNAL DISTRIBUTION**

1 - LOCAL PDR Lyons & Rochester, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm 8-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
16 ACRS SENT TO LIC ASST S. Sheppard		
** SEND ONLY TEN DAY REPORTS		

1948-1949  
1947-1948  
1946-1947

1948-49

1947-48

1946-47

1945-46

1944-45

1943-44  
1942-43  
1941-42

1940-41

1939-40

1938-39

1937-38

1936-37

1935-36




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

NEW YORK STATE

December 2, 1975



Regulatory

File Cyl

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Unusual Event 75-10, Unresponsive Emergency Generator Governor  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.6.2b, the attached report of Unusual Event 75-10 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.


Very truly yours,

*L.D. White, Jr.*

L. D. White, Jr.

Attachment

cc: Mr. Donald F. Knuth (30)  
Mr. William G. McDonald (3)



13583





Licensee Event Report  
Unusual Event 50-244/75-04

PORC Recommendations

1. Check wiring of emergency generator metering.
2. Perform test procedure PT-12.1 Emergency Diesel Generator 1A to the extent necessary to observe proper indicated response to generator governor control once each calendar week with appropriate personnel to observe the generator start and operation, to include station mechanics and electricians. This is to begin on the following day, 11/7/75, and continue until the next scheduled monthly surveillance.

Remedial Action Taken

1. The appropriate personnel have checked and tightened all connections of the emergency generator metering wiring.
2. Satisfactory response has been demonstrated on each of the five tests conducted following the incident.

This action is being documented in Corrective Action Report CAR-1047.

