

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1506

FILE: INCIDENT REPORT

FROM: Rochester Gas & Electric Corp Rochester, N.Y. Lee S. Lang		DATE OF DOC 2-19-75	DATE REC'D 2-10-75	LTR xxx	TWX	RPT	OTHER
TO: Mr. J.P. O'Reilly		ORIG no	CC 1	OTHER	SENT AEC PDR <u>xxxx</u>		SENT LOCAL PDR <u>xxx</u>
CLASS xxxxxx	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-244		
DESCRIPTION: Ltr reporting abnormal occurrence #75-02 concerning failure of the C Safety Injection Pump to Start Manually from Bus 16				ENCLOSURES:			
PLANT NAME: RE Gina #1							

FOR ACTION/INFORMATION 2-12-75 JGB

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/ Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506-A MUNTING/STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR FILE & REGION T.R. WILSON	<u>TECH REVIEW</u> SCHROEDER MACCARRY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA STEELE VOLIMER	<u>DENTON</u> GRIMES GAMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC. ASST.</u> DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE D. THOMPSON (2) KLEGKER F. WILLIAMS
--	---	---	---	---

EXTERNAL DISTRIBUTION

1-LOCAL PDR Lynons, NY, Rochester (2) (2) (10)	1-NATIONAL LABS	1-PDR SAN/LA/NY
1-TIC (ABERNATHY) NY	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN) RM B-127 G.T.
1-NEWTON ANDERSON		1-J. RUNKLES, RM E-201 G.T.
5-ACRS SENT TO LIC. ASST. S. Sheppard		

10-10-10

10-10-10 10-10-10 10-10-10 10-10-10

10-10-10 10-10-10 10-10-10 10-10-10

10-10-10 10-10-10 10-10-10 10-10-10

10-10-10 10-10-10 10-10-10 10-10-10

10-10-10 10-10-10 10-10-10 10-10-10




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649



NEW YORK STATE

TELEPHONE
AREA CODE 716 546-2700
Ginna Station
February 5, 1975



~~Encl.~~ No Cy.

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Abnormal Occurrence 75-02 - Failure of the 1C Safety Injection Pump to Start Manually from Bus 16
Ginna Station Docket #50-244

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. John Hannon this morning to report Abnormal Occurrence 75-02 at Ginna Station.

While conducting Periodic Test (PT-2.1), and following the satisfactory test of the 1-A and 1-B Safety Injection Pumps, the 1-C Safety Injection Pump which can be operated from either Bus 14 or Bus 16, failed to start manually on Bus 16 the first time it was tried. The 1-C pump was started from Bus 14 and the pump test completed. The pump was tried from Bus 16 twice since the malfunction and operated successfully.


The PORC met and recommended a thorough inspection of the breaker by the Electricians. Any further action that is necessary will be carried out after the Electricians report back to PORC.

Very truly yours,

Lee S. Lang
Assistant Superintendent

LSL:bg

cc: Mr. J. F. O'Leary, NRC
Mr. G. J. Swarthout, RG&E
Mr. L. D. White, Jr. RG&E



1506

