

50-244

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: MR J P O'TEILLY

FROM: ROCHESTER GAS & ELEC CORP
ROCHESTER, NY
L D WHITE, JR

DATE OF DOCUMENT
5-25-76

DATE RECEIVED
5-28-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP .

INPUT FORM

NUMBER OF COPIES RECEIVED
1 SIGNED

DESCRIPTION

LTR REF THEIR 4-23-76 RO 76-12 30-DAY REPORT...
ADVISING CORRECTIVE ACTION IS PLANNED TO PLACE
KEEPERS ON THE PACKING GLAND NUTS TO PREVENT
ROTATION.....

ENCLOSURE

DO NOT REMOVE
ACKNOWLEDGED

1 PG

PLANT NAME: RE Ginna #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY	FOR ACTION/INFORMATION	ENVIRO
<input checked="" type="checkbox"/> BRANCH CHIEF:	PURPLE	
W/3 CYS FOR ACTION		
<input checked="" type="checkbox"/> LIC. ASST:	SHEPPARD	
W/ CYS		
ACRS 16 CYS HOLDING	SENT TO LA	

INTERNAL DISTRIBUTION	
<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (2)	
<input checked="" type="checkbox"/> MIPC (3)	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES/SCHWENCER	1 EACH
<input checked="" type="checkbox"/> CASE	
XXXXXXXXXX	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOLLMER/BUNCH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION	CONTROL NUMBER
<input checked="" type="checkbox"/> ROCHESTER, NY	5404
<input checked="" type="checkbox"/> LPDR: LYONS, NY	
<input checked="" type="checkbox"/> TIC	
<input checked="" type="checkbox"/> NSIC	


1944

.....

.....



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649




LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

Regulatory Docket File

May 25, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406



Subject: Supplemental Report on Reportable Occurrence 76-12, 30-day report, dated April 23, 1976
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

On April 23, 1976 we submitted Reportable Occurrence 76-12, 30-day report, Containment Personnel Airlock Handwheel Shaft Seal Excessive Leakage During Testing. In that report the statement was made that action to prevent a recurrence of that event was being investigated.

This is to inform you that the corrective action planned is to place keepers on the packing gland nuts to prevent them from rotating with the shaft, precluding their loosening and permitting leakage through the packing. These keepers will be installed at a future plant outage when the door assemblies can be dismantled for this maintenance.

In addition, procedure changes have been submitted to require as initial conditions that a mechanic verify proper seating of the packing gland nut prior to performing the applicable tests.

Two additional copies of this letter are enclosed to conform to the original submittal of Reportable Occurrence 76-12, 30-day report.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

5404

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

