



April 17, 1978
L-78-137

Central File
50-389

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-389

In response to IE Bulletin 78-02, unprotected terminal blocks will not be used on safety related systems inside the containment at St. Lucie Unit 2. Post LOCA qualification documentation on cable splices will be provided in the St. Lucie Unit 2 FSAR.

Very truly yours,

J. A. De Mastry
for
Robert E. Uhrig
Vice President

REU:JNB:sl

cc: Harold F. Reis, Esquire

AO 2
60