



April 17, 1978  
L-78-137

*Central File*  
*50-389*

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389

In response to IE Bulletin 78-02, unprotected terminal blocks will not be used on safety related systems inside the containment at St. Lucie Unit 2. Post LOCA qualification documentation on cable splices will be provided in the St. Lucie Unit 2 FSAR.

Very truly yours,

*J. A. De Mastry*  
*for*  
Robert E. Uhrig  
Vice President

REU:JNB:sl

cc: Harold F. Reis, Esquire

*AO 2*  
*60*