



February 2, 1987

50-281

Mr. L. S. Rubenstein, Director
PWR Project Directorate No. 2
Division of PWR Licensing-A
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Rubenstein:

The attached Westinghouse report, Surry Unit 2 J-Tube Examination, is being forwarded to you per our previous conversation. The report contains Westinghouse proprietary information, please handle appropriately.

If you require additional information, please let me know.

Very truly yours,

R. J. Hardwick, Jr.
Manager - Nuclear
Programs and Licensing

Attachment

PA01
Add: L.S. Rubenstein Ltr Encl 11

8702050335 870202
PDR ADOCK 05000281
PDR



Westinghouse
Electric Corporation

Power Systems

Service Technology Division

Box 3377
Pittsburgh Pennsylvania 15230-3377

STD-2.4-7008
VPA-87-509

January 21, 1987

Mr. W. R. Matthews, Supervisor
Operations and Maintenance Support
Virginia Power
P. O. Box 26666
Richmond, VA 23261

SUBJECT: Request to Release J-Tube Report

Dear Bill:

We have received your request to release Westinghouse Report SG-83-09-050 entitled, Surry 2 J-Tube Examination. You may release the contents of this report to the NRC for use in evaluating the erosion-corrosion phenomenon that led to the pipe rupture at Surry.

Should you have any questions, please do not hesitate to contact me.

Very truly yours,

R. N. Easterling, Manager
Virginia Power Steam Generator
Maintenance Program

cc: Mr. J. L. Wilson
Mr. D. R. Beynon - Westinghouse-MNC