

**Virginia Electric And Power Company  
Surry Power Station  
5570 Hog Island Road  
Surry, Virginia 23883**

April 22, 1998

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Serial No.: 98-244  
SPS: JDK  
Docket No.: 50-280  
50-281  
License No.: DPR-32  
DPR-37

Dear Sirs:

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Units 1 and 2.

Report No. 50-280/1998-006-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



D. A. Christian  
Site Vice President

Enclosure

Commitments contained in this letter:

1. Inspect RCP thermowell caps for those thermowells that do not have the new RTD with system pressure capabilities.
2. Install a new high-pressure RTD in the Unit 1 B RCP thermowell during the next Refueling Outage.
3. During future scheduled RCP Motor change outs (normally one per Refueling Outage) the remaining original design RTDs will be replaced with the new high-pressure RTDs.

9804270416 980422  
PDR ADOCK-05000280  
S PDR

1620

cc: U. S. Nuclear Regulatory Commission  
Region II  
Atlanta Federal Center  
61 Forsyth Street, SW, Suite 23T85  
Atlanta, Georgia 30303

Mr. R. A. Musser  
NRC Senior Resident Inspector  
Surry Power Station