

10CFR50.73

**Virginia Electric And Power Company
Surry Power Station
5570 Hog Island Road
Surry, Virginia 23883**

MARCH 29, 1999

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No.: 99-144
SPS:CGL
Docket No.: 50-280
50-281
License No.: DPR-32
DPR-37


Dear Sirs:

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Units 1 and 2.

Report No. 50-280, 50-281/1999-002-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



E. S. Grecheck
Site Vice President

Enclosure

Commitments contained in this letter:

1. A review of the procedures used in the repair or maintenance of fire barriers will be conducted to verify that the UFSAR requirements to restore functionality, as well as the manufacturer's recommendations regarding cure times and inspections, are properly reflected.

9904060205 990329
PDR ADOCK 05000280
S PDR

cc: U. S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, Georgia 30303

Mr. R. A. Musser
NRC Senior Resident Inspector
Surry Power Station