

**ATTACHMENT 1**

**VIRGINIA ELECTRIC AND POWER COMPANY**

**SURRY POWER STATION UNIT 2**

**1993 ANNUAL STEAM GENERATOR  
INSERVICE INSPECTION REPORT**

**VIRGINIA ELECTRIC AND POWER COMPANY**

9403070285 940223  
PDR ADCK 05000280  
Q PDR

SURRY UNIT 2, APRIL 1993 RFO  
S/G "B", EDDY CURRENT EXAMINATION SUMMARY

---

In Steam Generator "B", 3342 tubes were inspected full length with bobbin probes. Supplemental examinations were also performed using Rotating Pancake probes where additional confirmatory or other data was desired. This included an examination of 301 tubes in the top of the tubesheet transition area. Of the tubes inspected, 91 tubes contained one or more indications. Two tubes were preventively plugged for anti-vibration bar wear. Including the plugged tubes, 30 tubes had indications between 20% and 29% through wall, 45 tubes had indications between 10% and 19% through wall, 20 tubes with 21 SAA signals, one tube with a PVN signal and one tube with a DRI signal. See the attached list for details.

**SURRY UNIT 2, APRIL 1993**  
**STEAM GENERATOR "B"**  
**EDDY CURRENT EXAMINATION**  
**INDICATION LIST**

<u>ROW</u>	<u>COL</u>	<u>LOCN</u>	<u>IND</u>	<u>REMARKS</u>
15	9	6H	16	
18	9	7C	SAA	
3	10	7C	22	
16	11	5C	14	
21	11	6H	13	
4	12	4H	13	
30	15	5H	14	
28	16	4C	25	
7	17	2C	PVN	
12	19	6C	21	
13	19	6H	16	
2	23	4C	17	
30	26	2H	15	
15	27	6H	11	
17	27	1H	17	
3	28	TSH	SAA	
13	28	6H	22	
28	31	6H	28	
43	31	2C	29	
18	35	3H	27	
2	36	1C	10	
3	36	2H	19	

**SURRY UNIT 2, APRIL 1993**  
**STEAM GENERATOR "B"**  
**EDDY CURRENT EXAMINATION**  
**INDICATION LIST**

<u>ROW</u>	<u>COL</u>	<u>LOCN</u>	<u>IND</u>	<u>REMARKS</u>
19	36	TSC	19	
21	36	TSH	15	
12	38	6C	19	
45	38	7H	11	
25	39	4H	15	
44	39	1C	10	
45	39	1C	17	
29	40	6H	19	
13	41	1H	11	
12	42	TSH	SAA	
26	42	2H	16	
10	43	TSC	10	
13	43	1H	25	
42	44	4H	15	
34	45	6H	15	
7	46	TSH	SAA	
14	46	6C	18	
34	46	BPC	14	
32	47	4C	15	
40	47	3C	21	
3	48	2C	16	
23	48	2C	24	

**SURRY UNIT 2, APRIL 1993**  
**STEAM GENERATOR "B"**  
**EDDY CURRENT EXAMINATION**  
**INDICATION LIST**

<u>ROW</u>	<u>COL</u>	<u>LOCN</u>	<u>IND</u>	<u>REMARKS</u>
45	48	6H	SAA	
9	50	4H	16	
19	50	TSH	SAA	
44	50	6H	13	
1	56	TSH	25	
9	56	6C	20	
9	56	TSH	SAA	
36	56	2C	14	
41	56	1C	23	
3	57	TSC	SAA	
17	57	5H	24	
17	57	4C	16	
25	57	6C	10	
41	57	4C	26	
34	58	4C	23	
36	58	2C	22	
41	58	6C	17	
42	58	1H	11	
4	59	4C	18	
4	59	TSC	SAA	
30	59	2C	22	
32	59	6C	27	
38	59	4C	12	

**SURRY UNIT 2, APRIL 1993**  
**STEAM GENERATOR "B"**  
**EDDY CURRENT EXAMINATION**  
**INDICATION LIST**

<u>ROW</u>	<u>COL</u>	<u>LOCN</u>	<u>IND</u>	<u>REMARKS</u>
24	60	2C	27	
40	60	AV3	20	plugged *
1	61	3H	SAA	
3	61	7H	SAA	
3	62	TSH	SAA	
3	62	3H	SAA	
38	62	7H	SAA	
20	63	7H	SAA	
33	63	AV2	20	plugged *
33	63	AV3	14	
3	64	4C	18	
12	64	TSH	SAA	
4	65	6C	29	
12	65	4C	13	
32	65	TEH	DRI	
32	65	7H	22	
3	66	TSH	SAA	
22	66	2C	27	
2	67	1H	22	
2	67	6H	SAA	
1	68	TSH	SAA	
20	69	1C	11	
4	72	2C	29	
37	74	4C	13	

SURRY UNIT 2, APRIL 1993  
STEAM GENERATOR "B"  
EDDY CURRENT EXAMINATION  
INDICATION LIST

<u>ROW</u>	<u>COL</u>	<u>LOCN</u>	<u>IND</u>	<u>REMARKS</u>
3	80	4C	27	
19	80	7H	SAA	
2	83	3C	24	
13	84	3C	14	
18	87	5C	21	
20	87	6C	10	
15	89	1C	SAA	

\* These tubes were preventively plugged.

**ATTACHMENT 2**

**GLOSSARY OF TERMS  
SURRY POWER STATION  
ANNUAL STEAM GENERATOR  
INSERVICE INSPECTION REPORT**

**VIRGINIA ELECTRIC AND POWER COMPANY**



**VIRGINIA ELECTRIC AND POWER COMPANY  
STEAM GENERATOR EDDY CURRENT TUBE INSPECTION**

**GLOSSARY OF TERMS**

1. ROW, COL - COLUMN - tube identifier numbers - an X-Y coordinate system.
2. IND - INDICATION - Character codes and numerics that represent the analysis results of the data for that tube, e.g., SAA, 25%, etc.
3. INF - Indication Not Found - Indicates that a previously reported Indication, from current inspection data or historical data, is not found in the data being analyzed - also used to address the case where a tube/signal is being retested for positive identification (PID) and the retest data does not show any signal present.
4. LOCN - LOCATION - The location in the tube of the INDICATION called.
5. DRI - DISTORTED ROLL TRANSITION INDICATION - A possible tube wall loss condition that is unquantifiable with a numeric percent call due to the signal characteristics and is located at the roll transition - often retested with RPC (Rotating Pancake Coil Probe).
6. 55 - A number in the indication column shows the % through wall depth of the indication.
7. PVN - PERMEABILITY VARIATION - A variance in the tube permeability that produces a signal that can mask other signals of interest.
8. SAA - SINGLE AXIAL ANOMALY - Describes a single axially oriented anomaly signal from RPC (Rotating Pancake Probe) data. The anomaly is based on metallurgical evaluation of tube pull data and is caused by lift-off from a slight inside diameter depression in the tube.
9. TEH - Tube End Hot leg.
10. TEC - Tube End Cold leg.
11. TSH - Top of Tubesheet Hot leg.
12. TSC - Top of Tubesheet Cold leg.
13. BPH, BPC - Baffle Plate Hot Leg and Cold Leg

VIRGINIA ELECTRIC AND POWER COMPANY  
STEAM GENERATOR EDDY CURRENT TUBE INSPECTION

GLOSSARY OF TERMS

14. #C, #H - (# = number) of Support Plate Hot or Cold leg.  
e.g., 3H, 6H, 7C.
15. AV1, AV2, AV3, AV4 - Anti-Vibration Bars 1 through 4.

Note: Where no comment appears in the remarks column the tube is still in service.

**ATTACHMENT 3**

**VIRGINIA ELECTRIC AND POWER COMPANY  
SURRY POWER STATION UNIT 2  
TUBESHEET MAPS**

**VIRGINIA ELECTRIC AND POWER COMPANY**

# S/G - B TUBES TO BE PLUGGED

× : 2 TUBES TO BE PLUGGED


Surry Unit 2

VIR-B SERIES 51F

03-29-1993

12:01 HRS.

SUPERTUBIN



# HOT LEG BOBBIN INDICATION DISTRIBUTION

Surry Unit 2

VIR-B SERIES 51F


03-29-1993

03:30 HRS.

SUPERTUBIN



- \* N : 95 NON-QUANTIFIABLE INDICATION (INDICATION TESTED WITH RPC)
- 2 : 10 20 % - 29 % INDICATION
- 1 : 20 10 % - 19 % INDICATION
- B : 1174 MANUFACTURE BUFF MARK
- \* : RPC Testing did not identify any of the "NQI" signals as flaws. These signals were reclassified into non-indication categories. A number of the "NQI"s were reclassified as MBMs.



# COLD LEG BOBBIN INDICATION DISTRIBUTION

Surry Unit 2

VIR-B SERIES 51F

03-29-1993

08:09 HRS.

SUPERTUBIN

- \* N : 80 NON-QUANTIFIABLE INDICATION  
(INDICATION TESTED WITH RPC)
  - 2 : 20 20% - 29% INDICATION
  - 1 : 25 10% - 19% INDICATION
  - B : 1187 MANUFACTURES BUFF MARK
- \* : Same note as hot leg map.

