

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

March 15, 1994

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 94-139
NL/RPC
Docket No. 50-280
License No. DPR-32

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 1
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the Surry Unit 1 "B" steam generator was completed during the 1994 refueling outage. In accordance with Surry Power Station Technical Specifications, Section 4.19.F.a, this letter provides notification of the steam generator tubes that were plugged during the outage. Although plugging was not required by Technical Specification requirements, the four tubes noted below were plugged as a precautionary measure in steam generator "B".

<u>ROW</u>	<u>COLUMN</u>
34	17
34	19
39	23
43	31

If you have any questions concerning these results, please contact us.

Very truly yours,



M. L. Bowling, Manager
Nuclear Licensing and Programs

cc: United States Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. W. Branch
NRC Senior Resident Inspector
Surry Power Station

9403220234 940315
PDR ADOCK 05000280
PDR

AD47 1/0