

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9308090018      DOC. DATE: 93/07/29      NOTARIZED: NO      DOCKET #  
 FACIL: 50-281 Surry Power Station, Unit 2, Virginia Electric & Power      05000281  
 AUTH. NAME      AUTHOR AFFILIATION  
 BOWLING, M.L.      Virginia Power (Virginia Electric & Power Co.)  
 RECIP. NAME      RECIPIENT AFFILIATION  
                                  Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Surry Power Station Unit 2 for 1993 Refueling  
Outage 2nd Interval, 3rd Period ISI."

DISTRIBUTION CODE: A047D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1+250  
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES: 1cy NMSS/SCDB/PM.      *See Report*      05000281

	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL
	PD2-2 LA	1				0	PD2-2 PD	1				1
	BUCKLEY, B	2				2						
INTERNAL:	ACRS	6				6	AEOD/DSP/ROAB	1				1
	NRR/DE/EMEB	1				1	NRR/EMCB	1				1
	NUDOCS-ABSTRACT	1				1	OC/LFDCB	1				0
	OGC/HDS2	1				0	<u>REG FILE</u> 01	1				1
	RES/DSIR/EIB	1				1						
EXTERNAL:	EG&G BROWN, B	1				1	EG&G RANSOME, C	1				1
	NRC PDR	1				1	NSIC	1				1
NOTES:		1				1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 20

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

July 29, 1993

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Serial No. 93-318  
NL/RPC  
Docket No. 50-281  
License No. DPR-37

Gentlemen:

**VIRGINIA ELECTRIC AND POWER COMPANY**  
**SURRY POWER STATION UNIT 2**  
**INSERVICE INSPECTION SUMMARY REPORT**  
**FOR THE 1993 REFUELING OUTAGE**

As set forth in the provisions of ASME Section XI, paragraph IWA-6230, enclosed is the Inservice Inspection Report for Surry Power Station Unit 2 for the 1993 refueling outage. This report is a summary of examinations performed during the outage to satisfy the requirements for the second inservice inspection interval.

In accordance with IWA-6220 of the 1980 Edition of ASME Section XI, Winter 1980 Addenda, a Form NIS-1, Owner's Report for Inservice Inspections, abstract of examinations performed, and an examination summary are provided with this report as Attachment 1. The NIS-2 Forms, Owner's Reports for Repairs or Replacements, are provided as Attachment 2.

Should you require more detailed information, the entire report will be maintained on file at the station and the corporate office.

Very truly yours,



M. L. Bowling, Manager  
Nuclear Licensing and Programs

Attachments

cc: U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N. W.  
Suite 2900  
Atlanta, Georgia 30323

Mr. M. W. Branch  
NRC Senior Resident Inspector  
Surry Power Station

060000

9308090018 930729  
PDR ADOCK 05000281  
Q PDR

AD47