

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

May 8, 1992

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 92-290
NL/RPC
Docket No. 50-280
License No. DPR-32

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 1
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the Surry Unit 1 "A" and "B" steam generators was completed during the 1992 refueling outage. In accordance with Surry Power Station Technical Specifications, Section 4.19.F.a, this letter provides notification of the steam generator tubes that were plugged during the outage.

In steam generator "A," two tubes (Row 13/Col 20 & Row 28/Col 41) were plugged as a precautionary measure. No tubes were plugged in steam generator "B" during the 1992 refueling outage.

If you have any questions concerning these results, please contact us.

Very truly yours,



W. L. Stewart
Senior Vice President - Nuclear

cc: United States Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. W. Branch
NRC Senior Resident Inspector
Surry Power Station

9205190266 920508
PDR ADDCK 05000280
PDR

A047
/0