

THE CHURCH OF  
**JESUS CHRIST**  
OF LATTER-DAY SAINTS

SPRINGFIELD MO FM GROUP  
1357 South Ingram Mill Road  
Springfield, Missouri 65804-0625  
Phone: 1-417-889-4136  
Facsimile: 1-417-889-2125


6/11/2018

Director of FSME  
Attn: GLTS  
USNRC  
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 6/11/2018 we transferred the self-luminous exit signs listed on the attached spreadsheet to Shield Source Inc, RR#5 Municipal Airport, Peterborough, Ontario, K9J 6X6, Canada with CNSC License #NSPFOL-12.00/2012. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Arlaine R. Bell 417-889-4136.

Sincerely,



Arlaine R. Bell

Encl.

## SERIAL NUMBER SPREADSHEET

Company Name <i>Spld FM Group</i>	Date <i>6/6/2018</i>	
Address 1 <i>357 S. Ingramm/R</i>	Isolite RMA # <i>FMACO 243219</i>	
Address 2	EWS Order # <i>FMACO 243220</i>	
Address 3	MTS Order #s	
City/State <i>Spld, MD</i>	Contact Name <i>Arbaine RBell</i>	
Zip/Post Code <i>21884</i>	Contact Phone <i>417-889-4136</i>	
Country <i>USA</i>	Contact FAX	
	Contact E-mail <i>arbaine.bell@ldschurch.org</i>	

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	<i>Shield</i>	<i>101</i>	<i>M0083</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
2	<i>Shield</i>	<i>101</i>	<i>M0089</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
3	<i>Shield</i>	<i>101</i>	<i>M0088</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
4	<i>Shield</i>	<i>101</i>	<i>M0085</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
5	<i>Shield</i>	<i>101</i>	<i>M0091</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
6	<i>Shield</i>	<i>101</i>	<i>M0090</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
7	<i>Shield</i>	<i>101</i>	<i>M0096</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
8	<i>Shield</i>	<i>101</i>	<i>M0097</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
9	<i>Shield</i>	<i>101</i>	<i>M0093</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
10	<i>Shield</i>	<i>101</i>	<i>M0062</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
11	<i>Shield</i>	<i>101</i>	<i>M0086</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
12	<i>Shield</i>	<i>101</i>	<i>M0094</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
13	<i>Shield</i>	<i>101</i>	<i>M0095</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
14	<i>Shield</i>	<i>101</i>	<i>M0092</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>
15	<i>Shield</i>	<i>101</i>	<i>M0084</i>	<i>1</i>	<i>1998</i>	<i>0.43 ci</i>

*\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

**Once we have received and processed this information an RMA number will be issued.**

**If you have more signs that this form holds, please copy additional pages and filling all necessary information.**

## SERIAL NUMBER SPREADSHEET

Company Name	Spfld FM Group	Date	6/6/2018
Address 1	1357 S. Ingram Mill Rd	Isolite RMA #	FMACQ 243219
Address 2		EWS Order #	FMACQ 243220
Address 3		MTS Order #s	
City/State	Springfield, MO	Contact Name	ArLaine R Bell
Zip/Post Code	65804	Contact Phone	417-889-4136
Country	USA	Contact FAX	
		Contact E-mail	arlaine.bell@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	Shield	101	M0087	1	1998	0.43 Ci
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

*\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible"; etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

**Once we have received and processed this information an RMA number will be issued.**

**If you have more signs that this form holds, please copy additional pages and filling all necessary information.**