

VOID SHEET

TO: License Fee Management Branch

FROM: RIII - Material Licensing Branch

SUBJECT: VOIDED APPLICATION

Control Number: 602758


Applicant: Mid-America Isotopes, Inc.

License Number: 24-26241-01MD

Docket Number: 030-31896

Date Voided: June 28, 2018

Reason for Void: The licensee in application dated March 27, 2018, (ML18089A270) and letter dated June 18, 2018 (ML18173A036), requested to add molybdenum-99 (Mo-99) to produce technetium-99m (Tc-99m) for radiopharmaceutical production using the Northstar Medical Radioisotopes, LLC (NorthStar) RadioGenix™ System. Specifically, the licensee requested a variance regarding approving the use of the RadioGenix™ System prior to the radiation safety officer (RSO) receiving adequate training/qualifications in accordance with the guidance, *NorthStar Medical Radioisotopes LLC, "RadioGenix Molybdenum-99m/Technetium-99m Generator System. Licensing Guidance for Medical Use Licensees, Medical use Permittees and Commerical Nuclear Pharmacies."* Based on discussions with the NorthStar RadioGenix™ System Working Group and MLB Branch Chief, it was determined that the RSO must receive the training and experience as stated in the RadioGenix™ System guidance, before issuance of the license. The licensee (RSO) was contact on June 28, 2018, and informed that they must obtain training in accordance with the RadioGenix™ System guidance. The RSO indicated that additional time will be required to schedule and receive the RSO training from NorthStar and agreed to voiding the licensing action. Based on discussions with the licensee and MLB Branch Chief, the action will be voided to allow the licensee the additional time to receive RSO training and submit the additional information as stated.


Signature

June 28, 2018
Date