

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-315

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 01/16/78
DATE RCVD: 01/24/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 0 ENCL 1

LICENSEE EVENT REPT (RO 50-315/78-01) ON 12/17/77 CONCERNING UNIT 2 C-D
EMERGENCY DIESEL GENERATOR (PWR SUPPLY FOR UNIT MOTOR DRIVEN AUXILIARY FEED
PUMP, TECH SPEC 3.7.1.2A) TRIPPED OVERSPEED.

PLANT NAME: COOK - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BRANCH CHIEF DAVIS**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
I & E**W/2 ENCL
SCHROEDER/IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAO**W/ENCL
KREGER/J. COLLINS**W/ENCL
L. CROCKER**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
HOUSTON**W/ENCL
GRIMES**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL:

LPDR'S
ST. JOSEPH, MI**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P

CONTROL NBR: 780240046

***** THE END *****

60
A0 4

... ..
... ..
... ..

... ..
... ..
... ..

... ..
... ..
... ..

... ..
... ..
... ..

... ..
... ..
... ..




INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

Rids 05
REGULATORY DOCKET FILE COPY

January 16, 1978



Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operation License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b; the following report is submitted:

RO 50-315/78-01

Sincerely;

D.V. Shaller
Plant Manager

/cjs

- cc: J.E. Dolan
- R.W. Jurgensen
- G.E. Lien
- R. Kilburn
- R.J. Vollen BPI
- K.R. Baker RO:III
- R.C. Callen MPSC
- P.W. Steketee, Esq.
- R. Walsh, Esq.
- G. Charnoff, Esq.
- G. Olson
- J.M. Hennigan
- PNSRC
- J.F. Stietzel
- Dir., IE (30 copies)
- Dir., MIPC (3 copies).

780240046

*A002/5 **
0/1

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

PLEASE PRINT ALL REQUIRED INFORMATION

01	M I D C C L	0 0 - 0 0 0 0 0 0 - 0 0	4 1 1 1 1 1	0 3
7 8 9	14	15 25	26 30	31 32

01	CONT	L	L	0 5 0 - 0 3 1 5	1 2 1 7 7 7	0 1 1 6 7 8
7 8	57 58	59	60	61 68	69 74	75 80

EVENT DESCRIPTION

02 ON DECEMBER 17, 1977, JANUARY 2 AND 7, 1978 THE UNIT 2 C-D EMERGENCY
 03 DIESEL GENERATOR (POWER SUPPLY FOR UNIT 1 MOTOR DRIVEN AUXILIARY
 04 FEED PUMP, TECHNICAL SPECIFICATION 3.7.1.2.a) TRIPPED ON OVERSPEED.
 05 EACH TRIP OCCURRED DURING A DIESEL START. IN ALL INSTANCES THE C-D
 06 DIESEL WAS RESTARTED AND OPERABLE. (RO-050-0315/78-01)

07	E E	F	E N G I N E	N	W 1 2 0	N
7 8 9 10	11	12	17	43	44 47	48

CAUSE DESCRIPTION

08 N/A
 09
 10

11	E	1 0 0	N/A	A	DIESEL TRIP
7 8 9	10	12 13	44	45	46 80

12	Z	Z	N/A	N/A
7 8 9	10	11	44	45 80

PERSONNEL EXPOSURES

13	0 0 0	Z	N/A
7 8 9	11	12	13 80

PERSONNEL INJURIES

14	0 0 0	N/A
7 8 9	11	12 80

OFFSITE CONSEQUENCES

15 N/A

LOSS OR DAMAGE TO FACILITY

16	Z	N/A
7 8 9	10	80

PUBLICITY

17 N/A

ADDITIONAL FACTORS

18 N/A

19 N/A

NAME: J.L. RISCHLING

PHONE: 616-465-5901, EXT.368

11/17/78

11/17/78

RECEIVED DOCUMENT
CONTROL DESK

21 ...
1978 JAN 20 PM 12 31

U.S. HRC
DISTRIBUTION SERVICES
BRANCH