

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 9062

FILE: INCIDENT REPORT FILE

| | | | | | | | | |
|--|----------------|-----------|------------------------|---|-----------|--|-----|-------|
| FROM: Florida Power & Light Co. Miami, Fla. 33101 Robert E. Uhrig | | | DATE OF DOC 8-18-75 | DATE REC'D 8-26-75 | LTR XX | TWX | RPT | OTHER |
| TO: Mr. George Lear | | | ORIG 1 signed | CC | OTHER | SENT AEC PDR <u>XX</u> SENT LOCAL PDR <u>XX</u> | | |
| CLASS | UNCLASS XXX | PROP INFO | INPUT | NO CYS REC'D 1 | | DOCKET NO: 50-250/251 | | |
| DESCRIPTION: Ltr re our 12-5-74 ltr:...furn suppl info on the failure of non-seismic category I systems equipment..... | | | | ENCLOSURES: <i>Do Not Remove</i> | | | | |
| PLANT NAME: Turkey Pt. Units 3 & 4 | | | | | | | | |

FOR ACTION/INFORMATION

DHL 8-28-75


| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L) W/ Copies | SCHWENCER (L) W/ Copies | ZIEMANN (L) W/ Copies | REGAN (E) W/ Copies |
| CLARK (L) W/ Copies | STOLZ (L) W/ Copies | DICKER (E) W/ Copies | LEAR (L) W/ Copies |
| PARR (L) W/ Copies | VASSALLO (L) W/ Copies | KNIGHTON (E) W/ Copies | SPELS W/ Copies |
| KNIEL (L) W/ Copies | PURPLE (L) W/ Copies | YOUNGBLOOD (E) W/ Copies | |

INTERNAL DISTRIBUTION


| | | | | |
|---|--|---|---|--|
| <u>REG FILE (2)</u> NRC PDR (2) OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE | <u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER | DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS | <u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E) | <u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER |
|---|--|---|---|--|

EXTERNAL DISTRIBUTION

| | | |
|--|--------------------------------|---|
| 1 - LOCAL PDR <u>Miami, Fla.</u> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN) Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201 GT |
| 1 - ACRS SENT TO LIC ASST S. Teets 8-28-75 | | |
| ** SEND ONLY TEN DAY REPORTS | | |



August 18, 1975
L-75-393



Regulatory Docket File

Mr. George Lear, Chief
Operating Reactors Branch #3
Division of Reactor Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Lear:

Re: Turkey Point Units 3 & 4 - Docket Nos. 50-250 & 50-251
Supplementary Report of Failure of Non-Seismic Equipment

Your letter of December 5, 1974, requested that we determine whether the failure of non-seismic category I systems could affect the performance of safety related equipment. Our initial response to your request was dated January 7, 1975. On page 3, we stated the following:

"In investigating the switchgear rooms, it was noted that a short run of low pressure steam piping (supply to the condenser water box air ejectors) runs through the Unit No. 4 switchgear room. The potential for failure of this piping and the resultant consequences will be evaluated and corrective action will be taken based on the evaluation."

The purpose of this supplementary report is to inform you that we have rerouted the steam line in question such that it no longer passes through the Unit 4 switchgear room. Plant Change/Modification 75-24 was issued to implement rerouting, and supporting documentation is contained in the completed PC/M package.

Very truly yours, .

A handwritten signature in cursive script that reads "Robert E. Uhrig".

Robert E. Uhrig
Vice President

REU:MAS:nch

cc: Jack R. Newman, Esq.