

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL**  
(TEMPORARY FORM)

CONTROL NO: 6566

FILE: \_\_\_\_\_

FROM: Florida Power & Light Co. Miami, Fla. 33101 R. E. Uhrig		DATE OF DOC 6-4-75	DATE REC'D 6-18-75	LTR XX	TWX	RPT	OTHER
TO: Mr. A. Giambusso		ORIG 1 signed	CC	OTHER	SENT NRC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-250		

DESCRIPTION: Ltr furnishing info re inspection of safety related hydraulic pipe restraints inaccessible during power operation.....

PLANT NAME: Turkey Pt. Unit 3

ENCLOSURES:

**Do Not Remove**  
**ACKNOWLEDGED**

FOR ACTION/INFORMATION DHL 6-18-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	✓ LEAP (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPIES W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	LPM W/ Copies

**INTERNAL DISTRIBUTION**

<del>REG FILE</del> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER  ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) M. DUNCAN	A/T IND. BRAITMAN SALTZMAN MELTZ  PLANS ✓ MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON
---	---	--	---	--

**EXTERNAL DISTRIBUTION**

- ✓ - LOCAL PDR Miami, Fla.
- 1 - TIC (ABERNATHY) (1)(2)(10)
- 1 - NSIC (BUCHANAN)
- 1 - ASLB
- 1 - Newton Anderson
- ✓ 1 - ACRS HOLDING SENT
- 1 - NATIONAL LABS \_\_\_\_\_
- 1 - W. PENNINGTON, Rm E-201 GT
- 1 - CONSULTANTS  
NEWMARK/BLUME/AGBABIAN
- 1 - PDR-SAN/LA/NY
- 1 - BROOKHAVEN NAT LAB
- 1 - G. ULRIKSON ORNL

14

6566

Florida Power & Light Co.  
Miami, Fla. 33101  
R. E. Wright

XX

6-4-72

6-4-72

Mr. A. Glambuso

I signed

XXX

For furnishing info re inspection  
of safety related hydraulic pipe restraints  
inaccessible during power operation.....


Turbine Pt. Unit 3

SHU 6-4-72


Miami, Fla.

DATE: 6-4-72

Regulatory Docket File



June 4, 1975  
L-75-282



Mr. Angelo Giambusso, Director  
Division of Reactor Licensing  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Giambusso:



TURKEY POINT UNIT NO. 3  
DOCKET NO. 50-250  
INSPECTION OF SAFETY RELATED  
HYDRAULIC PIPE RESTRAINTS INACCESSIBLE  
DURING POWER OPERATION

The subject inspection was completed during a scheduled outage on May 25, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed all but one restraint to be in satisfactory condition. The adjusting turnbuckle locknuts for one of the feedwater piping restraints had vibrated loose allowing the turnbuckle to rotate until the linkage parted. The turnbuckle was reinstalled and the locknuts tightened prior to returning the unit to operation.

Very truly yours,

*Robert E. Uhrig*  
Robert E. Uhrig  
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

6566

