

FROM: Florida Power & Light Co. Miami, Fla. Robert E. Uhrig		DATE OF DOC 5-14-75	DATE REC'D 5-19-75	LTR XX	TWX	RPT -E	OTHER 313
TO: A. Giambusso		ORIG 1 Signed	CC	OTHER	SENT AEC PDR <u>XXX</u>		
					SENT LOCAL PDR <u>XXXX</u>		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-250		

DESCRIPTION:

Ltr. Re our ltr. of 11-8-73.....Advising subject inspection completed on 4-26-75,....showing two Restraints located on main steam piping had fluid levels below min. allowable level.....

PLANT NAME: Turkey Point # 3

ENCLOSURES:

ACKNOWLEDGED
DO NOT REMOVE

FOR ACTION/INFORMATION

VCR-5-23-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPRIS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	LICENSTNG PROJECT MANAGER W/ Copies


INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE <u>REG OPR</u> FILE & REGION (2) MPIC STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR <u>HARLESS</u>	<u>LIC ASST.</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON
---	--	--	---	--

EXTERNAL DISTRIBUTION


- 1 - LOCAL PDR *Homestead & Co*
- 1 - TIC (ABERNATHY) (1)(2)(10)
- 1 - NSIC (BUCHANAN)
- 1 - ASLB
- 1 - Newton Anderson
- 1 - ACRS HOLDING/SENT *Ingram*
- 1 - NATIONAL LABS
- 1 - W. PENNINGTON, Rm E-201 GT
- 1 - CONSULTANTS
NEWMARK/BLUME/AGBABIAN
- 1 - PDR-SAN/LA/NY
- 1 - BROOKHAVEN NAT LAB
- 1 - G. ULRIKSON, ORNL
- 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT
- 1 - J. D. RUNKLES, Rm E-201
GT

Hydrol. Dept.





May 14, 1975
L-75-230



Mr. Angelo Giambusso, Director
Division of Reactor Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Giambusso:

Re: Turkey Point Unit No. 3
Docket No. 50-250
Inspection of Safety Related Hydraulic
Pipe Restraints Accessible During Power Operation

The subject inspection was completed on April 26, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that two restraints located on the main steam piping had fluid levels below the minimum allowable level. These restraints were replaced with spare units.

Very truly yours,

J. A. De Mastry
for

Robert E. Uhrig
Vice President

REU:HNP:nch

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire



5521



THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
5800 S. UNIVERSITY AVENUE
CHICAGO, ILLINOIS 60637
TEL: 773-936-3700

TO: [Name] [Address] [City] [State] [Zip]
FROM: [Name] [Address] [City] [State] [Zip]

RE: [Subject]

[Text]

[Text]

[Text]

[Text]