


MEETING NOTICE DISTRIBUTION

✓ Docket Files 50-251

NRC PDR
Local PDR
ORB#3 Rdg
NRR Rdg
EGCase
VStello
KRGoller
DEisenhut
ASchwencer
DDavis
GLear
RReid
LShao
WButler
BGrimes
RBaer
WMcDonald
Project Manager
OELD
OI&E (3)
OSD (3)
BFaulkenberry

CParrish
Receptionist
NRC Participants
ACRS (16)



10/28/77

MEMORANDUM FOR: George Lear, Chief, Operating Reactors Branch #3, DOR
FROM: Richard Clark, Operating Reactors Branch #3, DOR
SUBJECT: FORTHCOMING MEETING WITH FLORIDA POWER & LIGHT COMPANY AND WESTINGHOUSE ON TURKEY POINT STEAM GENERATOR REPAIR

TIME & DATE: Wednesday, November 9, 1977
1:00 p.m.

LOCATION: Room P-422

PURPOSE: To discuss the design improvements proposed for the replacement steam generators for Turkey Point including:

1. Improved moisture separators (newdemister vanes, perforated plates, etc).
2. Use of Type 405 ferretic stainless steel for support plates.
3. Quatrefoil design for tube support plate interface.
4. Thermal treatment of Inconel 600 tubes.
5. Recessing tube to tube sheet weld.
6. Expanding tube to full depth of tubesheet.
7. Increasing recirculation ratio.
8. Increased number of hand holes.
9. Improved tube bundle accessibility.
10. Improved flow distribution.
11. Modifications to feeding.
12. Installing tube lane blocking devices

A

| | | | | | | |
|-----------|--|--|--|--|--|--|
| OFFICE > | | | | | | |
| SURNAME > | | | | | | |
| DATE > | | | | | | |

1961-1962

1961-1962

1961-1962

- 13. Modified blowdown arrangement
- 14. Improved resistance to sludge buildup.
- 15. Addition of 2" line for wet layup.
- 16. Addition of closure plates in channel head.
- 17. Improved quality assurance procedures.
- 18. Improved fabrication and welding procedures.
- 19. Improved control of condensate and feedwater water chemistry to reduce secondary side corrosion.

PARTICIPANTS: FP&L

Doug Whittier, Jack DeMastry, Jim Walden, Fred Flugger, et. al.

Westinghouse

Dave Marbinger, et al

NRC

Joe Reece, George Lear, Larry Shao, Dick Clark, Dick Stuart, Bob LaGrange, Frank Almeter, B. D. Liaw, Bart Buckley

Richard Clark, Project Manager
Operating Reactors Branch #3
Division of Operating Reactors

DISTRIBUTION:
See attached list

| | | | | | | |
|-----------|------------|--|--|--|--|--|
| OFFICE > | ORB#3 | | | | | |
| SURNAME > | RClark:acr | | | | | |
| DATE > | 10/ /77 | | | | | |



The first part of the document
 discusses the importance of
 maintaining accurate records
 and the role of the
 committee in overseeing
 the process. It also
 mentions the need for
 transparency and
 accountability in all
 actions taken.

The second part of the document
 outlines the specific
 responsibilities of the
 committee members and
 the procedures for
 reporting and
 reviewing the work.

The third part of the document
 provides a summary of the
 findings and recommendations
 made by the committee.

The committee believes that
 these measures are essential
 for ensuring the integrity
 of the process.

Signed: _____
 Date: _____