

50-251

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr Stello

FROM: Florida Pwr & Light Co  
Miami, Fla  
R E Uhrig

DATE OF DOCUMENT

4-19-76

DATE RECEIVED

4-22-76

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

one signed

DESCRIPTION

Ltr furnishing info concerning inspection of SNUBBERS on 3-20-76.....

ENCLOSURE

PLANT NAME: Turkey Point #4

SAFETY

FOR ACTION/INFORMATION

ENVIRO

4-28-76

ehf

ASSIGNED AD :

ASSIGNED AD :

BRANCH CHIEF :

BRANCH CHIEF :

PROJECT MANAGER:

PROJECT MANAGER :

LIC. ASST. :

LIC. ASST. :

*Lear (5)  
Elliot  
Parrish*

INTERNAL DISTRIBUTION

REG FILE

SYSTEMS SAFETY

PLANT SYSTEMS

ENVIRO TECH

NRC PDR

HEINEMAN

TEDESCO

ERNST

I & E (2)

SCHROEDER

BENAROYA

BALLARD

OELD

LAINAS

SPANGLER

GOSSICK & STAFF

ENGINEERING

IPPOLITO

MIPC

MACCARY

SITE TECH

CASE

KNIGHT

OPERATING REACTORS

GAMMILL

HANAUER

SIHWELL

STELLO

STEPP

HARLESS

PAWLICKI

OPERATING TECH

HULMAN

PROJECT MANAGEMENT

REACTOR SAFETY

EISENHUT

SITE ANALYSIS

BOYD

ROSS

SHAO

VOLLMER

P. COLLINS

NOVAK

BAER

BUNCH

HOUSTON

ROSZTOCZY

SCHWENCER

J. COLLINS

PETERSON

CHECK

GRIMES

KREGER

MELTZ

HELTEMES

AT & I

SITE SAFETY & ENVIRO

SKOVHOLT

SALTZMAN

ANALYSIS

RUTBERG

DENTON & MULLER

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Miami, Fla

NATL LAB

BROOKHAVEN NATL LAB

TIC

REG. V-IE

ULRIKSON (ORNL)

NSIC

LA PDR

ASLB

CONSULTANTS

ACRS 10 HOLDING/SENT

TO LA Parrish

4026




Handwritten scribble or mark at the top center.

103 2 30

.....

00-1-3




April 19, 1976  
L-26-161

Director of Nuclear Reactor Regulation  
Attn: Mr. Victor Stello, Jr., Director  
Division of Operating Reactors  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Stello:

**TURKEY POINT UNIT 4  
DOCKET NO. 50-251  
INSPECTION OF SAFETY RELATED  
HYDRAULIC PIPE RESTRAINTS  
LOCATED OUTSIDE CONTAINMENT**



The subject inspection was completed on March 20, 1976 in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973.


All safety related hydraulic pipe restraints located outside containment were in satisfactory condition.

Very truly yours,

*Robert E. Uhrig*  
Robert E. Uhrig  
Vice President

REU/MAS/jn

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire



4026

