

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. V. Stello
NRC

FROM: Florida Power & Light Co.
Miami, Fla. 33101
Robert E. Uhrig

DATE OF DOCUMENT
2-5-76

DATE RECEIVED
2-12-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1

DESCRIPTION Ltr furn info on inspection of safety related hydraulic pipe restraints located outside the containment....

PLANT NAME: Turkey Pt. Unit 4

ENCLOSURE

Do Not Remove

ACKNOWLEDGED

SAFETY FOR ACTION/INFORMATION ENVIRO DHL 2-19-76

ASSIGNED AD :		ASSIGNED AD :
BRANCH CHIEF :	LEAR (5)	BRANCH CHIEF :
PROJECT MANAGER:		PROJECT MANAGER :
LIC. ASST. :	PARRISH	LIC. ASST. :

INTERNAL DISTRIBUTION

REG FILE	SYSTEMS SAFETY	PLANT SYSTEMS	ENVIRO TECH
NRC PDR	HEINEMAN	TEDESCO	ERNST
I & E (2)	SCHROEDER	BENAROYA	BALLARD
OELD		LAINAS	SPANGLER
GOSSICK & STAFF	ENGINEERING	IPPOLITO	
MIPC	MACCARY		SITE TECH
CASE	KNIGHT	OPERATING REACTORS	GAMMILL
HANAUER	SIHWEIL	STELLO	STEPP
HARLESS	PAWLICKI		HULMAN
		OPERATING TECH	
PROJECT MANAGEMENT	REACTOR SAFETY	EISENHUT	SITE ANALYSIS
BOYD	ROSS	SHAO	VOLLMER
P. COLLINS	NOVAK	BAER	BUNCH
HOUSTON	ROSZTOCZY	SCHWENCER	J. COLLINS
PETERSON	CHECK	GRIMES	KREGER
MELTZ			
HELTEMES	AT & I	SITE SAFETY & ENVIRO	
SKOVHOLT	SALTZMAN	ANALYSIS	
	RUTBERG	DENTON & MULLER	

EXTERNAL DISTRIBUTION

LPDR: Miami, Fla.	NATL LAB	BROOKHAVEN NATL LAB
TIC	REG. V-IE	ULRIKSON(ORNL)
NSIC	LA PDR	
ASLB	CONSULTANTS	
ACRS/6 HOLDING/SENT	To L.A.	

CONTROL NUMBER

1389

10-10-50

Dear Mr. [Name]
[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]

[Faded text]


[Faded text]



Regulatory Docket File

February 5, 1976
L-76-48

Director of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Jr., Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Dear Mr. Stello:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS
LOCATED OUTSIDE CONTAINMENT

The subject inspection was completed on January 19, 1976, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973.

All safety related hydraulic pipe restraints located outside containment were in satisfactory condition.

Very truly yours,

Robert E. Uhrig
Vice President

REU/MAS/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire



