

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 13159

FILE: \_\_\_\_\_

FROM: Florida Power & Light Co Miami, Fla. 33101 Robert E. Uhrig		DATE OF DOC 11-10-75	DATE REC'D 11-18-75	LTR XX	TWX	RPT	OTHER
TO: Mr. Roger Boyd		ORIG 1 signed	CC	OTHER	SENT NRC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: .50-251		

DESCRIPTION: Ltr furn info on inspection of safety related hydraulic pipe restraints located outside the containment...

ENCLOSURES:

~~DO NOT REMOVE~~  
**ACKNOWLEDGED**

PLANT NAME: Turkey Pt. Unit 4

FOR ACTION/INFORMATION DHL 11-20-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies	REID (L) W/ COPIES
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAB (L) W/ Copies	
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPIES W/ Copies	
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	LPM Elliott W/ Copies	

**INTERNAL DISTRIBUTION**

<b>REG FILE</b> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC	<b>TECH REVIEW</b> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER  ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR <b>HARLESS</b>	<b>LIC ASST</b> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUGHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<b>A/T IND.</b> BRAITMAN SALTZMAN MELTZ  <b>PLANS</b> MCDONALD CHAPMAN DUBE (Ltr) E. COUPEL PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON
--	--	---	---	---

**EXTERNAL DISTRIBUTION**

- ✓ 1 - LOCAL PDR Miami, Fla.
- 1 - TIC (ABERNATHY) (1)(2)(10) - NATIONAL LABS
- 1 - NSIC (BUCHANAN)
- 1 - ASLB
- 1 - Newton Anderson
- 16 ACRS ██████████ SENT TO L.A.
- 1 - W. PENNINGTON, Rm E-201 GT
- 1 - CONSULTANTS  
NEWMARK/BLUME/AGBABIAN
- 1 - PDR-SAN/LA/NY
- 1 - BROOKHAVEN NAT LAB
- 1 - G. ULRIKSON ORNL

*[Handwritten signature]*

... ..



... ..

...

...

...

Regulatory Docket File



November 10, 1975

L-75-547



Director of Nuclear Reactor Regulation  
Attention: Mr. Roger Boyd, Acting Director  
Division of Reactor Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Boyd:

TURKEY POINT UNIT 4  
DOCKET NO. 50-251  
INSPECTION OF SAFETY RELATED  
HYDRAULIC PIPE RESTRAINTS  
LOCATED OUTSIDE CONTAINMENT

The subject inspection was completed on October 24, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that all but one of fifteen restraints inspected were in satisfactory condition. One restraint located on a 30 inch Main Steam line had less than the minimum acceptable fluid level and was replaced with a spare unit.

Very truly yours,

*J. A. De Mastry*  
*jr*

Robert E. Uhrig  
Vice President

REU/MAS/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

13159

