

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. V. Stello

FROM: FPL
Miami, Fla. 33101
R. E. Uhrig

DATE OF DOCUMENT
7-20-76

DATE RECEIVED
7-23-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1 signed

DESCRIPTION Ltr furn info on inspection of safety related hydraulic pipe restraints....

ENCLOSURE

PLANT NAME: Turkey Pt. Unit 4

ACKNOWLEDGED

DO NOT REMOVE

SAFETY

FOR ACTION/INFORMATION

ENVIRO

DHL 7-28-76

ASSIGNED AD:		ASSIGNED AD:
<input checked="" type="checkbox"/> BRANCH CHIEF: (5) LEAR		BRANCH CHIEF:
<input checked="" type="checkbox"/> PROJECT MANAGER: Elliott		PROJECT MANAGER:
<input checked="" type="checkbox"/> LIC. ASST.: PARRISH		LIC. ASST.:

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	SYSTEMS SAFETY	PLANT SYSTEMS	SITE SAFETY &
<input checked="" type="checkbox"/> NRC PDR	HEINEMAN	TEDESCO	ENVIRO ANALYSIS
<input checked="" type="checkbox"/> I & E (2)	SCHROEDER	BENAROYA	DENTON & MULLER
OELD		LAINAS	
GOSSICK & STAFF	ENGINEERING	IPPOLITO	ENVIRO TECH.
<input checked="" type="checkbox"/> MIPC	MACCARRY	KIRKWOOD	ERNST
CASE	KNIGHT		BALLARD
HANAUER	SIHWEIL	OPERATING REACTORS	SPANGLER
HARLESS	PAWLICKI	STELLO	
			SITE TECH.
PROJECT MANAGEMENT	REACTOR SAFETY	OPERATING TECH.	GAMMILL
BOYD	ROSS	EISENHUT	STEPP
P. COLLINS	NOVAK	SHAO	HULMAN
HOUSTON	ROSZTOCZY	BAER	
PETERSON	CHECK	BUTLER	SITE ANALYSIS
MELTZ		GRIMES	VOLLMER
HELTEMES	AT & I		BUNCH
SKOVHOLT	SALTZMAN		J. COLLINS
	RUTBERG		KREGER

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/> LPDR: Miami, Fla.	NAT LAB:	BROOKHAVEN NAT LAB	7444
TIC:	REG. VIE	ULRIKSON(ORNL)	
NSIC:	LA PDR		
ASLB:	CONSULTANTS		
<input checked="" type="checkbox"/> ACRS 16 CYS SENT TO L.A.			

100

100

100

100

FOR THE YEAR

100

100

100


100

100

100

100

100



Regulatory Docket File

July 20, 1976
L-76-266

Director of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Jr., Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Stello:

TURKEY POINT UNIT 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS



The subject inspection was completed on June 2, 1976 in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection showed that all but one of the safety related hydraulic pipe restraints located inside the containment were in satisfactory condition. The fluid level on a feedwater line restraint indicated below the specified value. This was caused by a slight loss of oil. However, there was sufficient oil left in the system to keep the restraint operable. The restraint was replaced by a spare unit.

Very truly yours,

for
Quin F. Pearson

Robert E. Uhrig
Vice President

REU/RSA/bfp

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire



7/24/76



— — —

...

