

08/08/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-220/251

REC: STELLO V
NRC

ORG: UHRIG R E
FL PWR & LIGHT

DOCDATE: 08/04/78
DATE RCVD: 08/07/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED
LTR 3 ENCL 40

SUBJECT: FORWARDING REVISION 5 TO APPLICANT'S STEAM GENERATOR REPAIR REPT WHICH WAS
SUBMITTED ON 09/20/77.

Revision, w/50-250

PLANT NAME: TURKEY PT #3
TURKEY PT #4

REVIEWER INITIAL: XJM
DISTRIBUTER INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LICENSE.
(DISTRIBUTION CODE A001)

FOR ACTION: BR CHIEF ORB#1 BC**W/7 ENCL

INTERNAL: REG FILE**W/ENCL
I & E**W/2 ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
REACTOR SAFETY BR**W/ENCL
EEB**W/ENCL
J. MCGOUGH**W/ENCL

NRC PDR**W/ENCL
OELD**LTR ONLY
CORE PERFORMANCE BR**W/ENCL
ENGINEERING BR**W/ENCL
PLANT SYSTEMS BR**W/ENCL
EFFLUENT TREAT SYS**W/ENCL

EXTERNAL: LPDR'S
MIAMI, FL**W/ENCL
TERA**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL


TTTroc App 2

DISTRIBUTION: LTR 40 ENCL 39
SIZE: 1P+39P


CONTROL NBR: 782200321

***** THE END *****

ccp



REGULATORY BURDEN FILE COPY



August 4, 1978
L-78-255

Office of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Director
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Stello:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Steam Generator Repair Report
Revision 5

Attached herewith is Revision 5 to our Steam Generator Repair Report which was forwarded to you on September 20, 1977 (L-77-206).

Revision 5 contains a new SGRR appendix and modifications to some existing SGRR pages. With regards to the latter, only the actual portion of the page to be changed is indicated by a revision bar on the margin.

The attached Revision 5 package consists of the following:

- (1) Responses to Mr. A. Schwencer's request for additional information dated April 13, 1978 are incorporated in the SGRR as Appendix C, (pages C-1-1 through C-4-4 plus page 3-8 and table 3.2-1);
- (2) Revisions to Chapters 2 and 5 to incorporate the necessitated changes as a result of the lower assemblies tube bundle being 8 inches shorter than presently described in the SGRR, (pages 2-2, 5-3, 5-4, 5-8, 5-11, 5-12 and 5-13 plus tables 2.1-1 and 5.1-2) and;
- (3) Incorporation of accident analyses scenarios for Section 5.2 of the SGRR to demonstrate that transports of the lower assemblies over the east plant road safety related buried facilities can be acceptably accommodated with both Unit 3 and Unit 4 operating, (pages 5-21, 5-21a and 5-21b);
- (4) Corrections to various pages, (pages 5-20, A-5-1, 5-19, A-6-2 and figure A.22-2).

Very truly yours,

Robert E. Uhrig
Vice President

REU:GDW:plt

cc: J.P. O'Reilly, Region II
Robert Lowenstein, Esquire

782200321

Handwritten note:
Aoor
5/3/40
REU
SR 5