

CHAIRMAN Resource

From: Tom Gurdziel <tgurdziel@twcny.rr.com>
Sent: Tuesday, October 09, 2018 8:24 AM
To: CHAIRMAN Resource
Cc: 'Ed Stronski'
Subject: [External_Sender] Event Number 53647 at Wolf Creek

Good morning,

This Event Report at Wolf Creek is poorly written. It tells me that the fuel oil transfer pump worked on 10/4 but did not run on 10/5. I am told they were doing something to the Halon system at that time. So what?

Has the jumper placement been questioned? Do they plan to fix the logic (or equipment) so that the fuel oil transfer pump will work?

Or is it acceptable at this site to not fix broken/inop equipment?

Thank you,

Tom Gurdziel



Virus-free. www.avast.com