	•	,		
NRC FORM 591M PART 1 (07-2012)*		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201	ETY INSPECTION REPORT	AND COMPLIANCE IN	ISPECTION	√
1. LICENSEE/LOCATION INSPECTED: Maryland Q.C. Laboratories, Inc. dba MQC Labs, Inc. 1550 S. Philadelphia Blvd. Aberdeen, Maryland 21001 REPORT NUMBER(S) 2018-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S) 030-32529	4. LICENSE NUMBER(19-28683-01	(S)	5. DATE(S) OF INSPECTI July 19, 2018 – Decer	
LICENSEE:	13-2000-01		July 19, 2016 - Decel	11Del 12, 2016
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
Statement of Corrective Actions				
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	e actions described by me to the Ins	spector will be taken to correct R 2.201 (corrective steps alrea	ady taken, corrective steps w	hich will be taken,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				Í
NRC INSPECTOR	Michael Reichard	Mish	I Renled	12/12/18
BRANCH CHIEF	Arthur Burritt	and	TU	17/17/18
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013)	G:\WBL Documents\WBL Inspe	ection Records\R19-28683-0	01.2018-001.doc

Michael Reichard

SUNSI Review Completed By:

/RA/

X Public

X Non-Sensitive