

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 1600 EAST LAMAR BOULEVARD ARLINGTON, TEXAS 76011-4511

January 24, 2019

Mr. Brad Sawatzke, Chief Executive Officer Energy Northwest MD 1023 P.O. Box 968 Richland, WA 99352

SUBJECT: COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION REPORT 05000397/2018403

Dear Mr. Sawatzke:

On December 13, 2018, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Columbia Generating Station. The NRC inspector discussed the results of this inspection with you and other members of your staff. The results of this inspection are documented in the enclosed report.

The NRC inspector did not identify any finding or violation of more than minor significance.

This letter, and its enclosure will be made available for public inspection and copying at <u>http://www.nrc.gov/reading-rm/adams.html</u> and at the NRC Public Document Room in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding."

If you choose to provide a response to this report that contains Security-Related Information, please mark your entire response "Security-Related Information – Withhold from Public Disclosure Under 10 CFR 2.390" (d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/**RA**/

Jeremy R. Groom, Chief Plant Support Branch 1 Division of Reactor Safety

Docket No.: 50-397 License No.: NPF-21

Enclosure: Inspection Report 05000397/2018403

U.S. NUCLEAR REGULATORY COMMISSION Inspection Report

Docket Number:	05000397
License Number:	NPF-21
Report Number:	05000397/2018403
Enterprise Identifier:	I-2018-403-0004
Licensee:	Energy Northwest
Facility:	Columbia Generating Station
Location:	Richland, Washington
Inspection Dates:	December 10, 2018 to December 13, 2018
Inspector:	M. Chambers, Physical Security Inspector
Approved By:	Jeremy R. Groom Chief, Plant Support Branch 1 Division of Reactor Safety

SUMMARY

The U.S. Nuclear Regulatory Commission (NRC) continued monitoring the licensee's performance by conducting a Baseline Security inspection at Columbia Generating Station, in accordance with the Reactor Oversight Process. The Reactor Oversight Process is the NRC's program for overseeing the safe operation of commercial nuclear power reactors. Refer to <u>https://www.nrc.gov/reactors/operating/oversight.html</u> for more information. Findings and violations being considered in the NRC's assessment are summarized in the table below. Licensee-identified non-cited violations are documented in the Inspection Results at the end of this report.

List of Findings and Violations

No findings or violations of more than minor significance were identified during the inspection.

INSPECTION SCOPES

Inspections were conducted using the appropriate portions of the inspection procedures (IPs) in effect at the beginning of the inspection unless otherwise noted. Currently approved IPs with their attached revision histories are located on the public website at http://www.nrc.gov/reading-rm/doc-collections/insp-manual/inspection-procedure/index.html. Samples were declared complete when the IP requirements most appropriate to the inspection activity were met consistent with Inspection Manual Chapter (IMC) 2201, "Security Inspection Program for Commercial Nuclear Power Reactors." The inspector reviewed selected procedures and records, observed activities, and interviewed personnel to assess licensee performance and compliance with Commission rules and regulations, license conditions, site procedures, and standards.

SAFEGUARDS

71130.02—Access Control (1 Sample)

The inspector evaluated the security access control program. The following elements were evaluated:

Tier I: all requirements Tier II: all requirements Tier III: all requirements

OTHER ACTIVITIES – BASELINE

71151—Performance Indicator Verification (1 Sample)

The inspector verified licensee performance indicators submittals listed below for the period from October 20, 2017 through October 1, 2018, Protected Area Security Equipment Performance Index.

(1) Protected Area Security Equipment Performance Index

EXIT MEETINGS AND DEBRIEFS

On December 13, 2018, the inspector presented the access control inspection results to Mr. Brad Sawatzke, Chief Executive Officer and other members of the licensee staff. The inspector verified no proprietary information was retained or documented in this report.

DOCUMENTS REVIEWED

71130.02 – Access Control

Condition Reports

00374945

00378932 00378932

Procedures		
Number	Title	Revision
SPIP-SEC-01	Sergeant and Lieutenant Duties	025
SPIP-SEC-02	Central and Secondary Alarm Stations	021
SPIP-SEC-05	Personnel Search Officer, Access Control/Security Communications Center Officer, Protected Area Access Point	036
SPIP-SEC-06	Vehicle Escort Officer, Vehicle Search Officer, and Protected Area Perimeter Gates	024
SPIP-SEC-10	Special Purpose Detectors, Operability Test, Inspection, and Maintenance Records	018
SPIP-SEC-19	Key and Lock Control	007
SPIP-SEC-26	Post 21 Checkpoint Procedures	035
SPIP-SEC-48	Itemizer 3 Explosive Detector	006
SPIP-SEC-51	Railroad Checkpoint and Security Search Procedures	004
SPIP-SEC-56	Datastrip Wireless Reader (DWR)	005
SPIP-SEC-63	Helicopter Landing in the SDOCA	000
SPIP-SEC-64	Warehouse X-Ray	002
SPIP-SEC-65	Access Authorization Program	009
SWP-SEC-01	Vital and Protected Area Key and Lock Control	007
SWP-SEC-03	Security Responsibilities of Site Personnel	029
SWP-SEC-08	Plant Key and Lock Control	003
SWP-SEC-12	Protected And Vital Area Personnel And Vehicle Access Controls	006
SWP-CAP-01	Corrective Action Program	39
CMI-03	Two-Man Rule	0
SPI-18	Compensatory Measures	15

Miscellaneous Documents Number	Title	Date
	016 Vital and Protected Area Key Core Inventory	March 6, 2018
	2017 Vital and Protected Area Key Core Inventory	March 6, 2018
	Event Log	October 20, 2017 to November 24, 2018
	Vital and Protected Areas Access List	November 27, 2018
	AU-SE-PADS-MRO-SAE-18 Audit Report	August 9, 2018
	Access Control Snap Shot Assessment	August 9, 2018
	Security Manning Roster	November 27, 2018
	Personnel Denied Access List	October 20, 2017 to November 27, 2018

71151—Performance Indicator Verification

Miscellaneous Documents			
Number	Title	Date	
	Security Equipment Normalization and Calculations	August 2017 to October 2018	

COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION REPORT 05000397/2018403 – JANUARY 24, 2019

Distribution w/enclosure:

EWharton, NSIR NSimonian, NSIR DGarner, NSIR DHuyck, NSIR DJohnson, NSIR RMcKinley, RI DRS BDesai, RII DRS SOrth, RIII DRS SMorris, ORA MShaffer, ORA AVegel DRP MHay, DRP RLantz, DRS GMiller, DRS JGroom, DRS GKolcum, DRP MBennettt, DRP LMerker, DRP MHaire, DRP RAlexander, DRP AAthar, DRP LNewman, DRP

Distribution w/o enclosure:

VDricks, ORA JKlos, NRR MHerrera, FRMB DCylkowski, ORA RKellar, DRS PJayroe, DRS JWeil, RIV/OCA AMoreno, RIV/OCA AMoreno, RIV/OCA ARivera-Varona, RIV/OEDO ACES GWalker, OI BMaier, ORA RidsOeMailCenter Resource

ADAMS ACCESSION NUMBER: ML19024A539								
SUNSI Review:	ADAMS:	□ Non-Publicly	Available	Non-Sensitive	Keyword:			
By: MLC	×Yes □No	*Publicly Availa	ble [☐ Sensitive				
OFFICE	PSI:PSB1	PSI:PSB1	C:PSB1	C:PBA	C:PSB1			
NAME	MChambers	RLanfear	JGroom	MHaire	JGroom			
SIGNATURE	/RA/	/RA/	/RA/	/RA/	/RA/			
DATE	1/24/19	1/24/19	1/24/19	1/24/19	1/24/19			

OFFICIAL RECORD COPY