

derick W. Schneider  
e President  
duction

Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/430-7373

February 9, 1978

Mr. Boyce H. Grier  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

NRC IE BULLETIN NO. 78-02  
TERMINAL BLOCK QUALIFICATION  
SALEM GENERATING STATION  
UNITS NOS. 1 AND 2  
DOCKET NO. 50-272/311

In compliance with the requests of the NRC, we have scrutinized our incontainment terminal block usage on those circuits which are required to function for post accident conditions. We find that we have no exposed terminal blocks.

Since this is the response to question 1, no other questions require responses.

Sincerely,



CC Director, Office of Nuclear  
Reactor Regulation  
Washington, D. C. 20555  
Director, Office of Reactor  
Operations Inspection  
Washington, D. C. 20555

