

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

MAR 04 2019

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

Serial No. 19-093
SPS-LIC/CGL R0
Docket No. 50-281
License No. DPR-37

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 2
INSERVICE INSPECTION OWNER'S ACTIVITY REPORT (OAR)

In accordance with the requirements of ASME Code Case N-532-5, Virginia Electric and Power Company (Dominion Energy Virginia) hereby submits the Inservice Inspection Owner's Activity Report (Form OAR-1) for Surry Unit 2 refueling outage S2R28, which ended on December 6, 2018. This document contains the reporting requirements for the first refueling outage of the second period in the fifth ten-year inservice inspection interval for Surry Unit 2.

If you have any questions concerning this information, please contact Mrs. Candee G. Lovett at (757) 365-2178.

Very truly yours,



Rob M. Garver II
Director Station Safety & Licensing
Surry Power Station

Attachment: Owner's Activity Report (Form OAR-1), Surry Unit 2 Refueling Outage S2R28, Second Period of the Fifth ISI Interval

Commitments made in this letter: None

A047
NRR

cc: U.S. Nuclear Regulatory Commission
Region II
Marquis One Tower
245 Peachtree Center Avenue NE
Suite 1200
Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector
Surry Power Station

Ms. K. Cotton Gross
NRC Project Manager – Surry
U. S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 08 G9A
11555 Rockville Pike
Rockville, Maryland 20852-2738

Mr. James R. Hall
NRC Senior Project Manager – North Anna
U.S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 08 G-9A
11555 Rockville Pike
Rockville, MD 20852-2738

Mr. R. A. Smith
Authorized Nuclear Inspector
Surry Power Station

Serial No.: 19-093
Docket No.: 50-281

ATTACHMENT

**OWNER'S ACTIVITY REPORT (FORM OAR-1),
SURRY UNIT 2 REFUELING OUTAGE S2R28,
SECOND PERIOD OF THE FIFTH ISI INTERVAL**

**VIRGINIA ELECTRIC AND POWER COMPANY
(DOMINION ENERGY VIRGINIA)**

CASES OF ASME BOILER AND PRESSURE VESSEL CODE
FORM OAR-1 OWNER'S ACTIVITY REPORT

CASE
N-532-5

Report Number 2-5-2-1 (Unit 2, 5th Interval, 2nd Period, 1st Report)
Plant Surry Power Station, 5570 Hog Island Road, Surry, VA 23883
Unit No. 2 Commercial service date 05/01/1973 Refueling outage no. S2R28
(if applicable)
Current inspection interval 5th
(1st, 2nd, 3rd, 4th, other)
Current inspection period 2nd
(1st, 2nd, 3rd)
Edition and Addenda of Section XI applicable to the inspection plans 2004 Edition
Date and revision of inspection plans Surry Unit 2, 5th Int. ISI Plan, Revision 5, January 2019
Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans _____
Code Cases used for inspection and evaluation: See ISI Plan for list of Code Cases
(if applicable, including cases modified by Case N-532 and later revisions)

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of S2R28 conform to the requirements of Section XI. (refueling outage number)

Signed R. J. Mitchell / ISI Program Owner Date 2/19/19
Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and employed by The Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

R. J. Smith Commissions NB-7933 NS, IS: VA883(R)
Inspector's Signature National Board, State, Province, and Endorsements
Date Feb. 21/2019

CASES OF ASME BOILER AND PRESSURE VESSEL CODE
FORM OAR-1 OWNER'S ACTIVITY REPORT

CASE
N-532-5

Table 1
Items with Flaws or Relevant Conditions That Required Evaluation for Continued Service

Examination Category and Item Number	Item Description	Evaluation Description
	None	

CASES OF ASME BOILER AND PRESSURE VESSEL CODE
FORM OAR-1 OWNER'S ACTIVITY REPORT

CASE
N-532-5

Table 2
Abstract of Repair/replacement Activities Required for Continued Service

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
1	02-RC-E-1A-HTEXCH	Primary manway stud identified with damaged threads. Replace one primary stud and nut.	11/15/2018	2018-182
3	02-SW-PP-48.00-WS-PIPE-102-10	Engineering identified one through-wall corrosion pit identified in line 48.00-WS-102-10.	11/11/2018	2018-178
3	02-SW-PP-8.00-WS-PIPE-488-21X	Perform weld repairs as instructed by Base Metal Repair sheet. Weld repair required on 8"-WS-488-21X weldolet connection to 36"-WS-104-10.	11/13/2018	2018-184