



Nuclear Division
4600 East Tech Dr. • Cincinnati, OH 45245
Phone: 513.528.7800 • Fax: 513.528.9292
www.CWNuclear.com

March 8, 2019

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

50-254/265

Subject: Interim Notification Report for Potential Part 21 update.

Dear Sir or Madam:

In reference to the Curtiss-Wright Interim Notification Report dated 10/8/2018 (Event No. ML18289A457/Log No. 2018-24-00) for an EA700-90964 limit switch failure, the following updates are provided.

Curtiss-Wright's investigation is ongoing, with the current focus being the evaluation of in-service switch operating temperatures and results from a recent disassembly/inspection of similar switches (same model but different date codes). Additional inspection of other switches currently in-service at the plant is needed to finish the investigation. Evaluation of these switches is expected to be completed by mid May. Once this data is made available, a final conclusion as to the root cause of the failure can be determined.

We therefore request additional time to complete our evaluation and should have our final report issued by May 31, 2019.

Sincerely:

Tim Franchuk
Director, Quality Assurance
Curtiss-Wright Nuclear Division, Cincinnati Operations
513-201-2176
TFranchuk@CurtissWright.com

IE19
NRR