

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

February 14, 1978

*Central File*

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II - Suite 818  
230 Peachtree Street, Northeast  
Atlanta, Georgia 30303

Serial No. 039A/011678  
PO&M/DLB:wbh  
Docket Nos: 50-280  
50-281  
50-338  
License Nos. DPR-32  
DPR-37  
NPF-4

Dear Mr. O'Reilly:

This is in response to IE Bulletin No. 78-01, "Flammable Contact-Arm Retainers in G.E. CR-120A Relays". A survey has been performed to determine if any G.E. CR120A relays are installed in any safety related equipment at our Surry Unit Nos. 1 and 2 or North Anna Unit No. 1. None of the subject relays were found to be installed in any safety related equipment. It has also been determined that no such relays are in the spares inventory or on order for these stations.

Yours very truly,

*C. M. Stallings*

C. M. Stallings  
Vice President - Power Supply  
and Production Operations

cc: HQ Staff Training/Qualifications  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

*aoz  
Wt*