

Central File

50-280  
50-281

**Veeco**

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station  
P.O. Box 315  
Surry, Virginia 23884

August 6, 1976

C.D. 8/5/76

Director of Regulatory Operations  
230 Peachtree Street  
Suite 818  
Atlanta, Georgia 30303

This is to inform you by telecopy of a Reportable Occurrence that was noted on August 5, 1976 at Surry Nuclear Power Station. An unreviewed safety question was identified by Westinghouse in that the rod bow penalty is higher than originally used, with a possible reduction of 8% in TNER.

*J.* Q. L. Stewart  
I. L. Baucom