

Central File

50-280
50-281

Veeco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23884

August 6, 1976

C.D. 8/5/76

Director of Regulatory Operations
230 Peachtree Street
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of a Reportable Occurrence that was noted on August 5, 1976 at Surry Nuclear Power Station. An unreviewed safety question was identified by Westinghouse in that the rod bow penalty is higher than originally used, with a possible reduction of 8% in TNER.

J. O. L. Stewart
I. L. Baucom