

**Veeco**

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station  
P.O. Box 315  
Surry, Virginia 23883

October 16, 1975


*D. Files*

*50-281/75-19*

Director of Regulatory Operations  
230 Peachtree Street, N. W.  
Suite 818  
Atlanta, Georgia 30303

This is to inform you by teletype of an abnormal occurrence that was noted on October 15, 1975 at Surry Nuclear Power Station.

With Unit #2 operating at 100% power, recirculation of the #2 Boron Injection Tank was interrupted for a period of 15 minutes due to the failure of the #2 Boron Cold Transfer Pump Motor. This is a violation of Technical Specification 3.2.3.4.

  
R. H. Gannaway, Jr.  
Manager