


VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

July 1, 1975



REGULATORY DOCKET FILE COPY

Mr. Norman C. Moseley, Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region II - Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Serial No. 586  
PO&M/JTB:clw  
Docket No. 50-281  
License No. DPR-37

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.1, the Virginia Electric and Power Company hereby submits forty (40) copies of Abnormal Occurrence Report No. A0-S2-75-10.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.


Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

Enclosures  
40 copies of A0-S2-75-10

cc: Mr. K. R. Goller



7238

# LICENSEE EVENT REPORT

AO-S2-75-10

CONTROL BLOCK: 

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

01	V	A	S	P	S	2	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	0	0	1
7	8	9	14	15	25	26	30	31	32																
01	CONT	P	0	T	L	0	5	0	-	0	2	8	1	0	6	2	4	7	5	0	6	2	6	7	5
7	8	57	58	59	60	61	68	69	74	75	80														

## EVENT DESCRIPTION

02 During normal operation on Unit No. 2, service water pump 2-SW-P-4B developed a seal  
03 leak. Water filled the valve pit containing the isolation valve MOV-SW-202B. Water  
04 caused electrical short in motor operator. MOV-SW-202A remained operable. Pump  
05 leak and motor operator were repaired. The above is contrary to Tech Spec 1.0.I.6.  
06 AO-S2-75-10

07	W	A	E	V	A	L	V	O	P	A	L	2	0	0	N
7	8	9	10	11	12	17	43	44	47	48					

## CAUSE DESCRIPTION

08 Limitorque motor operator SMB-000. Water leaking from pump ran across floor and into  
09 valve pit filling the pit with water and flooding motor of MOV-SW-202B. Floor  
10 plating above pit will be sealed to prevent a recurrence.

11	E	1	0	0	N/A	A	N/A							
7	8	9	10	12	13	44	45	46						

12	Z	Z	N/A	N/A										
7	8	9	10	11	44	45								

## PERSONNEL EXPOSURES

13	0	0	0	Z	N/A									
7	8	9	11	12	13									

## PERSONNEL INJURIES

14	0	0	0	N/A										
7	8	9	11	12										

## OFFSITE CONSEQUENCES

15 N/A

## LOSS OR DAMAGE TO FACILITY

16	Z	N/A												
7	8	9	10											

## PUBLICITY

17 N/A

## ADDITIONAL FACTORS

18 N/A

19

NAME: E. M. Sweeney, Jr.

PHONE: (804) 357-3184