

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23883

February 18, 1975

Director of Regulatory Operations
230 Peachtree Street
Suite 818
Atlanta, Georgia 30303

This is to inform you by teletype of an Abnormal Occurrence that was noted on February 15, 1975 at Surry Nuclear Power Station.

Unit 1 Overpower AT low level amplifier failed causing inoperable Overpower AT protection.

E. M. Sweeney, Jr.

E. M. Sweeney, Jr.
Station Manager