



July 16, 2019

ULNRC-06515

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 73.71(a)(4)

Ladies and Gentlemen:

**DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
UNION ELECTRIC CO.
RENEWED FACILITY OPERATING LICENSE NPF-30
LICENSEE EVENT REPORT 2019-004-00
SECURITY MEASURE SUSPENDED DUE TO SEVERE WEATHER**

The enclosed licensee event report is submitted in accordance with 10 CFR 73.71(a)(4) to report suspension of security measures on May 21, 2019 and May 22, 2019. These actions were needed during severe weather to protect the personal health and safety of security force personnel.

This letter does not contain new commitments.

Sincerely,

Mark McLachlan
Senior Director, Plant Support

Enclosure

The continuation sheets (Form 366A) of the enclosure to this letter (i.e., pages 2, 3 and 4 of 4) contain sensitive information. Withhold from public disclosure under 10 CFR 2.390. Upon removal of the continuation sheets, this letter and page 1 of the enclosure (Form 366) are uncontrolled.

cc: Mr. Scott A. Morris
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. L. John Klos
Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop O9E3
Washington, DC 20555-0001

Director
Division of Security Policy
Office of Nuclear Security and Incident Response
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Index and send hardcopy to QA File A160.0761

Hardcopy:

Certrec Corporation

6100 Western Place, Suite 1050

Fort Worth, TX 76107

(Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

Electronic distribution for the following can be made via LER ULNRC Distribution:

F. M. Diya

B. L. Cox

F. J. Bianco

T. E. Herrmann

S. P. Banker

M. A. McLachlan

R. C. Wink

T. B. Elwood

B. Brown

J. Reed

Corporate Oversight

NSRB Secretary


Performance Improvement Coordinator

Resident Inspectors (NRC)

STARS Regulatory Affairs

Mr. Jay Silberg (Pillsbury Winthrop Shaw Pittman LLP)

Missouri Public Service Commission

NRC FORM 366 (04-2018)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB: NO. 3150-0104	EXPIRES: 03/31/2020
 LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov , and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.	
1. Facility Name Callaway Plant Unit 1		2. Docket Number 05000483	3. Page 1 of 4
4. Title Security Force Positions Evacuated due to Severe Weather Announcement			
5. Event Date			8. Other Facilities Involved
6. LER Number		7. Report Date	
Month Day Year	YEAR Sequential Number Rev No.	Month Day Year	Facility Name Docket Number
05 21 2019	2019 - 004 - 00	07 16 2019	Facility Name Docket Number 05000
05 22 2019			Facility Name Docket Number 05000
9. Operating Mode		11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)	
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(iii)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)
10. Power Level	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(A)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input checked="" type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)
		<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 73.77(a)(1)
		<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 73.77(a)(2)(i)
		<input checked="" type="checkbox"/> OTHER	<input type="checkbox"/> 73.77(a)(2)(ii)
Specify in Abstract below or in NRC Form 366A			
12. Licensee Contact for this LER			
Licensee Contact T.B. Elwood, Supervising Engineer, Regulatory Affairs and Licensing		Telephone Number (Include Area Code) 314-225-1905	
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT			
Cause	System	Component	Manufacturer
Reportable to ICES	Cause	System	Component
Manufacturer	Reportable to ICES	Manufacturer	Reportable to ICES
14. Supplemental Report Expected			15. Expected Submission Date
<input type="checkbox"/> Yes (If yes, complete 15. EXPECTED SUBMISSION DATE)			Month Day Year
<input checked="" type="checkbox"/> No			
ABSTRACT (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)			
On 05/21/2019 at approximately 1655 hours, security measures were suspended due to impending severe weather.			
On 05/22/2019 at approximately 2348 hours, security measures were again suspended due to impending severe weather.			
The suspension of security measures was made per the provisions of 10 CFR 73.55(p)(1)(ii) and must be reported and documented in accordance with the provisions of 10 CFR 73.71. One-hour event notifications were made and documented for these two events per Event Notifications 54076 and 54081. This report serves as the 60-day written report required by 10 CFR 73.71(a)(4) and 10 CFR 73.71(d), for both events.			