



LER 78-041/3L

Cause Description and Corrective Actions

It was realized upon PORC review of this incident on June 7, 1978 that this failure constituted a valid failure and that the Technical Specifications require testing at an increased frequency. Testing at the increased frequency was implemented on June 7, 1978.

60-322