

License No. CPPR-66

APPENDIX A

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on June 25 and 26, 1975, it appears that one of your activities was not conducted in full compliance with conditions of your NRC Facility License No. CPPR-66 as indicated below:

Contrary to 10 CFR 50.55(e):

The identification, by magnetic particle examination, of axial linear indications in reactor coolant pump studs and nuts was not promptly reported to the Nuclear Regulatory Commission.

This item is an infraction and had the potential for causing or contributing to an occurrence related to health and safety.

7904210719

64-091