

APPENDIX A

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on July 29 - August 1, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your NRC Facility License No. CPPR-66 as indicated below:

1. Contrary to 10 CFR 50, Appendix B, Criterion IX and PSAR Table 3.2-1:

Reactor Coolant Piping weld RC-038 was observed to have a v-notch at the fusion line between the base metal and the weld deposit whereas the applicable code USAS B31.7 requires that the weld surface merge smoothly with the component.

This item is an infraction and had the potential for causing or contributing to an occurrence related to health and safety.

2. Contrary to 10 CFR 50, Appendix B, Criterion V and PSAR, Paragraph 17.1.8.4:

A spool piece in the waste disposal gas piping system was installed without the heat number identification as required by Procedure QCP-8-2.

This item is a deficiency.

7904210727