

APPENDIX A

NOTICE OF VIOLATIONS

Metropolitan Edison Company
P. O. Box 542
Reading, Pennsylvania 19603
Docket No. 50-289

Based on the results of the WRC inspection conducted on July 28-30 and August 3 and 4, 1976, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your NRC Facility License No. DPR-50, as indicated below. These items are categorized as Deficiencies.

- A. Section 5.5.1 of the Environmental Technical Specifications (ETS) requires, in part, that written procedures be prepared to ensure compliance with various activities involved in carrying out the provisions of the ETS. One of these activities is the analyses of background and indicator station air samples for I-131 and radioactive particulates.

Contrary to this requirement, written procedures have not been prepared to ensure compliance with the ETS with regard to the analysis of I-131 and radioactive particulates in air samples.

- B. Section 4.4.a of the ETS requires, in part, that quarterly gamma spectral analysis be performed on the composites of the eight weekly indicator air particulate sample stations and of the one weekly background air particulate sample station.

Contrary to this requirement, weekly air particulate samples were not composited as described above, for the quarterly background samples since 1974.

Other deficiencies identified through your internal audit program and which were reported (if required) and corrected or in which corrective action was initiated, are identified in the inspection report. No additional information is needed for these items at this time.

790051

7908230629