

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | O | F | S | V | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 2 | 0 | 4 | _____ | 5

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 7 | 7 | 0 | 8 | 1 | 7 | 7 | 9 | 8 | 0 | 8 | 3 | 1 | 7 | 9 | 9

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On August 17, 1979, while operating at approximately 50% of rated power it was deter-

0 3 | mined that a recent pipe hanger installation on the PCRV cooling water lines would

0 4 | have prevented proper installation of pipe spools to the high temperature filter ad-

0 5 | sorber coolers. These are required to be installed and operable within 1 1/2 hours of

0 6 | an extended loss of forced circulation. This does not meet the requirements of Fort

0 7 | St. Vrain Technical Specifications LOO 4.2.18 and is reportable per AC 7.5.2(a)5.

0 8 | _____

0 9 | SYSTEM CODE: C B (11) CAUSE CODE: B (12) CAUSE SUBCODE: C (13) COMPONENT CODE: S U P P O R T (14) COMP. SUBCODE: A (15) VALVE SUBCODE: Z (16)

17 | LER/RO REPORT NUMBER: 7 9 (21) SEQUENTIAL REPORT NO.: 0 2 7 (24) OCCURRENCE CODE: 0 1 (27) REPORT TYPE: T (30) REVISION NO.: 0 (32)

ACTION TAKEN: B (18) FUTURE ACTION: A (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (22) ATTACHMENT SUBMITTED: Y (23) NPRD-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: G 0 6 3 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Hanger additions to the system piping caused the pipe ends to change alignment and

1 1 | made the spool pieces inoperable. The spool pieces were modified to fit on the

1 2 | available purification train and will be modified on the other train after it is re-

1 3 | moved from service. There was no affect on public safety or health.

1 4 | _____

1 5 | FACILITY STATUS: E (28) % POWER: 0 5 0 (29) OTHER STATUS: N/A (30) METHOD OF DISCOVERY: C (31) DISCOVERY DESCRIPTION: In House Audit (32)

1 6 | ACTIVITY RELEASED: Z (33) CONTENT: Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)

1 7 | PERSONNEL EXPOSURES: NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: N/A (39)

1 8 | PERSONNEL INJURIES: NUMBER: 0 0 0 (40) DESCRIPTION: N/A (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY: TYPE: Z (42) DESCRIPTION: N/A (43)

2 0 | PUBLICITY ISSUED: N (44) DESCRIPTION: N/A (45)

NAME OF PREPARER: J. W. Gahm J. W. Gahm PHONE: (303) 785-2253

930320
7909100575