

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	Z	I	S	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	31	CAT		58

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 3 0 4 7 0 8 0 6 7 9 8 0 8 3 0 7 9 9 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Operators discovered that S/G level 2LI-538 read over 4% higher
0 3 (2% per channel limit) than other channels. This is non-conservative
0 4 for low-low S/G trip and low S/G coincident with steam/feed flow
0 5 (ref TS table 3.1-1.17 and 18). Bistables were tripped per AOP-9. As
0 6 redundant protection was available and operational, the health and
0 7 safety of the public were not affected.

08 790 81

0 9 11 12 13 14 15 16

(17) LER RO REPORT NUMBER 7 9 —

EVENT YEAR 0 4 1 /

SEQUENTIAL REPORT NO. 0 3 —

OCCURRENCE CODE 1 —

REPORT TYPE 0 —

REVISION NO. 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM 500	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C	Z	Z	Z	0000	N	Y	N	H015		
33	34	35	36	37	41	42	43	44		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Mechanics discovered that Hagan power supply model 4111085-G01 S.N.
1 1 M0584 drifted from 46v to 49v; exceeding the transmitter manufacturer's
1 2 recommendations. The power supply was replaced and the loop returned
1 3 to normal. Since this is not a recurring problem, no further action
is planned.

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION					
1	5	E	28	0'9'2	29	NA	A	31	Operator observation	32

ACTIVITY CONTENT
RELEASED OF RELEASE

1	6	2	3	NA
7	8	9	10	11

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

45	80
----	----

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	21	35	NA	39

PERSONNEL INJURIES		NUMBER		DESCRIPTION		943		121	
1	2	3	4	5	6	7	8	9	10
7	8	9	10	11	12				

LOSS OF OR DAMAGE TO FACILITY		(43)	
TYPE	DESCRIPTION		
1 0	2 (42) NA		7909120 466

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	11	NA			
7	8	9	10				

NAME OF PREPARER Paul Hansen

PHONE: (312) 746-2084 Ext. 344

POOR ORIGINAL